



5401 W. Mercer Way ~ Bonney St. Storm Drains

Location	Inspector
5401 W. Mercer Way Mercer Island WA	Todd Vecchio Todd@SoundSewerinspection.com 206-619-9990



3/14/2021



3/13/2021 10:22:06 AM

0"

Pipe is approx. 2.5 feet in depth. Video of drain #1:
<https://youtube.com/watch?v=-m30-NWTca8>



3/13/2021 10:27:08 AM

9"

Video of drain #2: <https://youtube.com/watch?v=O0Gn4iibkDU>



3/13/2021 10:27:38 AM

1' 0"

Drain #2 has a catch basket for debris/leaves. The basket was NOT removable to pipe inspection.



3/13/2021 10:27:32 AM

1' 2"



3/13/2021 10:29:29 AM

2' 10"

Drain #3 has a catch basket for debris/leaves. The basket was NOT removable to pipe inspection. Video of drain #3: <https://youtube.com/watch?v=X2EZozW7nro>



3/13/2021 10:33:15 AM

4' 5"

Drain #4, pipe is approx. 4' feet in depth. Video of drain #4: <https://youtube.com/watch?v=aZpbgnsvg7o>



3/13/2021 10:35:04 AM

42' 8"

Major debris in the lower drain

10:34:57 AM / 03-13-2021

3/13/2021 10:34:57 AM

44' 5"

Major blockage down the line. Sewer scope camera can not get past this point in the line.



[44' 5"]