

February 29, 2024

COMMENT RESPONSE LETTER

RE: 2401-129  
5330 LANSDOWNE LANE

1. Soil bearing has been revised to coordinate with structural
2. Setbacks are labeled on the site plan
3. Math errors have been fixed
4. Patio removed from hardscape
5. The OFFICE has been relabeled SLEEPING ROOM
6. Make-up air note added to appliance schedule sheet 3.1
7. Smoke detectors and carbon monoxide detectors are shown
8. Spaces where no work is to occur are labeled.
9. Fans are shown
10. No 12' ceilings.

Regards,

---

Dave Buck, architect