



Similar height and location fences all along West Mercer Way







Similar height and location fences all along West Mercer Way







Similar height and location fences all along West Mercer Way







Similar height and location fences all along West Mercer Way







Similar height and location fences all along West Mercer Way







Similar height and location fences all along West Mercer Way







Similar height and location fences all along West Mercer Way







Existing fence of similar height and location (along West Mercer Way and an adjacent improved street) located on the Ellis property immediately south.



Existing fence of similar height and location (along West Mercer Way and an adjacent improved street) located on the property immediately north of Dr. Jack.





Recently approved fence and gate project of similar height and location (along West Mercer Way and an adjacent improved street) currently under construction three homes south of our property.



View looking north from the top of Eden Lane, where there is already an existing fence of similar height, located closer to West Mercer Way than our intended fence, gate, and planned vegetation.





Existing fence of similar height and location within the Eden Lane neighborhood. A significant portion of this fence (installed by the former owners of our neighbor to the west within the last 4 years) runs along the shared access driveway used by Harnisch and Cook families. Our intended fence would be of very similar height and location to this existing fence and therefore would not alter the character of the neighborhood.







Similar height gates located on or just off of West Mercer Way







Similar height and location gates all along West Mercer Way







Recently approved gate of similar size, height, and location will be installed on this driveway just three homes south of our property.





Multiple views looking north from the top of the shared access driveway used by the Harnisch and Cook families illustrating the turning vantage point.

Our intended fence and gate will be located to the left of the west most cone and therefore will not obstruct the view of oncoming West Mercer Way traffic at all. In the distance, our northern neighbor's cedars extend well east of our intended fence, gate, and planned vegetation.





View looking north from the top of Eden Lane, illustrating the turning vantage point.

Our intended fence, gate, and planned vegetation will be located well west of the power pole and cannot be seen at all from the top of Eden Lane and therefore will not affect the view of oncoming traffic at all.





View of Eden Lane adjacent to the NW corner of our property. No part of our intended fence is visible (it will be located further east), indicating no impairment to the view of the road or trouble negotiating the corner much further west (to address the comment by Mrs. Cook)








This is the view looking east towards the Jack and Jennings property at approximately the top of our intended gate and fence. Much of the view west is obstructed by vegetation at the west end of their property.





Clear footprint marking on the front door indicated forced entry



Damage to the top and bottom of the doors as a result of forced entry



Repairs to the inside of the front door to prevent further forced entry

