









# **MONACO VILLA** EXTERIOR REMEDIATION

2929 76th Ave SE, Mercer Island, WA 98040


01/24/24 DESIGN COMMISSION

REVISION SCHEDULE			
REV	DATE	DESCRIPTION	

2215901

## CURRENT CONDITIONS







# **MONACO VILLA** EXTERIOR REMEDIATION

2929 76th Ave SE, Mercer Island, WA 98040

01/24/24 DESIGN COMMISSION


REVISION SCHEDULE			
REV	DATE	DESCRIPTION	


2215901

### ORIGINAL DESIGN PRESENTATION














2 EAST ELEVATION VIEW 1/16" = 1'-0"



(1) AERIAL VIEW FROM SOUTHEAST



#### COLOR PALETTE:

MAIN BODY PAINT: CULTURED PEARL ACCENT PAINT: MOUNT ETNA TRESPA: ROMANTIC WALNUT ACCENT ENTRY: REUSED COPPER PANELS

## SW 7625: MOUNT ETNA








SW 6028: CULTURED PEARL



# **MONACO VILLA** EXTERIOR REMEDIATION

2929 76th Ave SE, Mercer Island, WA 98040


01/24/24 DESIGN COMMISSION




2215901

UPDATED DESIGN USING COMMENTS









# **MONACO VILLA** EXTERIOR REMEDIATION

2929 76th Ave SE, Mercer Island, WA 98040

01/24/24 DESIGN COMMISSION

REVISION SCHEDULE				
REV	DATE	DESCRIPTION		

2215901

ENLARGED AERIAL VIEW

