
# SITE PLAN



Pin: 012404-9011

Legal Description: POR OF GL 6 & OF LOT 16 ROANOKE ADD LY S OF FOLG LN BAAP IN S LN SD LOT N 88-31-08 W 150.04 FT FR W LN OF W MERCER WAY TH S 89-36-40 W 105.59 FT TH N 89-31-46 W 49.93 FT TH N 71-21-09 W 27.15 FT TH N 62-33-56 W 72.94 FT TO SHOF LK WA & ELY LN OF SH LDS TH N 44-50-16 W TO WLY MGN SD SH LDS & TERMINUS SD LN & LY NLY OF FOLG LN BAAP IN WLY MGN OF W MERCER WAY FR NXN WITH N LN SD GL 6 BEARS N 28-35-52 E 356.39 FT SD PT BEING EQUI DISTANT FR SD NXN & NXN SD WLY MGN WITH N LN SE 22ND ST (MENAGE AVE) PROD ELY TH N 44-35-07 W ALG LN THAT WOULD BI-SECT MDR LN TAP EQUI DISTANT MEAS ALG SD MDR LN FR WLY TERM OF SD N LN & NLY TERM OF W LN SD GL 6-312.51 FT TH N 02-14-17 W 27.29 FT TH N 46-27-50 W 80.77 FT TO SH LN TH & ELY LN OF SH LDS TH N 44-50-16 W TO WLY LN SD SH LDS & TERMINUS SD LN & LYING NWLY OF W MERCER WAY LESS ST HWY

Plat Block: N/A Plat Lot: N/A

LAT: 47.59254 LONG: -122.2476



ABOR ESTD 1947

Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119


Office: 206-236-1700 ext. 3 www.seabornpiledriving.com Scope of Work: We propose to repair (10) piles and repair the dock with grated decking material.


SHEET A1.0

Adjacent Owners: KITTILSBY TIM & LISA 2029 W MERCER WAY 98040

ast Updated: 12/22/2021 10:33 AM Dray

COUNTY: KING COUNT IN: LAKE WASHINGTON





# PIER DETAILS - EXISTING/PROPOSED

## **EXISTING MEMBERS**


- (35) EXISTING PILES
- (10) EXISTING CAPS
- (60) EXISTING STRINGERS

(105) TOTAL EXISTING MEMBERS

## MEMBERS TO BE REPAIRED

- (10) EXISTING PILES TO BE REPAIRED
- (10) EXISTING CAPS TO BE REPAIRED
- (32) EXISTING STRINGERS TO BE REPAIRED
- (52) TOTAL EXISTING MEMBERS TO BE REPAIRED

105/52 = 49% OF EXISTING MEMBERS TO BE REPAIRED



**PLAN VIEW** 



Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119


Office: 206-236-1700 ext. 3 www.seabornpiledriving.com Scope of Work: We propose to repair (10) piles and repair the dock with grated decking material.

SHEET A4.0


Adjacent Owners: KITTILSBY TIM & LISA 2029 W MERCER WAY 98040


COUNTY: KING COUNT IN: LAKE WASHINGTON

SHORELINE



# **BMP INFORMATION**





### **BMP NOTES:**

- Constant vigilance shall be kept for the presence of protected fish species during all aspects of the proposed action, particularly during in-water activities such as vessel movement, deployment of anchors & spuds, pile driving, dredging, and placement of gravels and other fill.
- 1. The project manager shall designate an appropriate number of competent observers to survey the project site and adjacent areas for protected species, including the presence of fish as conditions allow.
- 2. Visual surveys shall be made prior to the start of work each day, and prior to resumption of work following any break of more than an hour. Periodic additional visual surveys throughout the work day are strongly recommended.
- 3. All in-water work shall be done during the in-water work window for the waterbody. Where there is a difference between the USCOE and WDFW work windows, the overlap of the two shall apply.
- 4. All pile driving and extraction shall be postponed or halted when obvious aggregations or schooling of fish are observed within 50 yards of that work, and shall only begin/resume after the animals have voluntarily departed the area.
- 5. When piloting vessels, vessel operators shall operate at speeds and power settings to avoid grounding vessels, and minimize substrate scour and mobilization of bottom sediments.
- No contamination of the marine environment shall result from project-related activities.
- 1. Appropriate materials to contain and clean potential spills shall be stored and readily available at the work site and/or aboard project-related vessels.
- 2. The project manager and heavy equipment operators shall perform daily pre-work equipment inspections for cleanliness and leaks. All heavy equipment operations shall be postponed or halted should a leak be detected, and shall not proceed until the leak is repaired and the equipment is cleaned.
- 3. To the greatest extent practicable, utilize biodegradable oils for equipment that would be operated in or
- 4. Fueling of land-based vehicles and equipment shall take place at least 50 feet away from the water, preferably over an impervious surface. Fueling of vessels shall be done at approved fueling facilities.
- 5. Turbidity and siltation from project-related work shall be minimized and contained through the appropriate use of erosion control practices, effective silt containment devices, and the curtailment of work during adverse weather and tidal/flow conditions.
- 6. All wastes shall be collected and contained for proper disposal at approved upland disposal sites appropriate for the material(s).
- 7. When removing piles and other similarly treated wood, containment booms must fully enclose the work area. Wood debris, oils, and any other materials released into lake waters must be collected, removed. and properly disposed of at approved disposal sites.
- 8. All in- and over-water wood cutting would be limited to the minimum required to remove the subject wood component, and all cutting work should be enclosed within floating containment booms.
- 9. When removing piles, no actions shall be taken that would cause adhering sediments to return to lake
- 10. Above-water containment shall be installed around removed piles to prevent sediment laden waters from returning to lake waters.
- 11. Construction staging (including stocking of materials, etc.) will occur on the supply barge.
- 12. All Exposed wood to be used on the project will be treated with a cheminite treatment.

**DETAIL 1.1 & 1.2** 

Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119

Office: 206-236-1700 ext. 3 www.seabornpiledriving.com Scope of Work: We propose to repair (10) piles and repair the dock with grated decking material.

SHEET A6.0

NWS-2021-76

Datum: CORPS OF ENGINEERS 1919 SW Quarter Of Section 1, Township 24, Range 04

Seaborn Pile Driving Company 1080 W Ewing St Seattle, WA 98119

APPLICANT:

PROJECT: Kittilsby, Lisa 2025 W. Mercer Way Mercer Island, WA 98040


Mercer Island, W COUNTY: KING COUNTY IN: LAKE WASHINGTON


ast Updated: 12/22/2021 10:33 AM

Owners: LISA WAY 98040

Adjacent ( KITTILSBY TIM & L 2029 W MERCER V

# MITIGATION PLAN





### Notes:

- 1. Shrubs are show, and shall be planted, at least five feet on center. Trees are show, and shall be planted, at least ten feet to center.
- 2. The property owner will implement and abide by the shoreline planting plan. The plants shall be installed before or concurrent with the work authorized by this permit. A report, as-built drawing and photographs demonstrating the plants have been installed or a report on the status of project construction will be submitted to the U.S. Army Corps of Engineers, Seattle District, Regulatory Branch, within 12 months from the date of permit issuance. This reporting requirement may be met by completing and submitting a U.S. Army Corps of Engineers approved Report for Mitigation Work Completion form.
- 3. The property owner will maintain and monitor the survival of installed shoreline plantings for five years after the U.S. Army Corps of Engineers accepts the as-built report. Installed plants shall achieve 100% survival during monitoring Years 1 and 2. Installed plants shall achieve at least 80% survival during monitoring Years 3, 4 and 5. Percent survival is based on the total number of plants installed in accordance with the approved riparian planting plan. Individual plants that die will be replaced with native riparian species in order to meet the survival performance standards.
- 4. The property owner will provide annual monitoring reports for five years (Monitoring Years 1-5). Each annual monitoring report will include written and photographic documentation on plant mortality and replanting efforts and will document whether the performance standards are being met. Photos will be taken from established points and used repeatedly for each monitoring year. In addition to photos at designated points, photo documentation will include a panoramic view of the entire planting area. Submitted photos will be formatted on standard 8 1/2 x 11" paper, dated with the date the photo was taken, and clearly labeled with the direction from which the photo was taken. The photo location points will be identified on an appropriate drawing. Annual shoreline planting monitoring reports will be submitted to the U.S. Army Corps of Engineers, Seattle District, Regulatory Branch, by November 31 of each monitoring year. This reporting requirement may be met by

Previous plantings from dock extension mitigation work under NWS-2021-76 to compensate here.

completing and submitting a U.S. Army Corps of Engineers approved Mitigation Planting Monitoring Report form. Seaborn Pile Driving Scope of Work: We propose to repair (10) piles and repair the dock with grated decking material. 1080 W Ewing St Seattle, WA 98119 Office: 206-236-1700 ext. 3



www.seabornpiledriving.com


HEET A7.0 SHE

Adjacent (
KITTILSBY TIM & L
2029 W MERCER V

Datum: CORPS OF ENGINEERS 1919 SW Quarter Of Section 1, Township 24, Range 04

ast Updated: 12/22/2021 10:33

COUNTY: KING COUNT IN: LAKE WASHINGTON



# **GENERAL NOTES:**

## MATERIALS SPEC LIST:

Decking Material: FRPP - Fiberglass reinforced polypropylene

Light permeable percentage:

- \* Surface 43%
- \* 18" Dock Height 61%

### Sewer:

\* All sewer is field verified by probing the lake bed manually during the allowed work windows for the area.

### Piles:

Repair piles are done as a sleeve/strap method

#### CODE REFERENCES: Mercer Island

#### "Development Standards for Replacement, Repair and Maintenance of Overwater Structures, Including Moorage Facilities" per MIMC 19.13050(F)(2).

- 2. Development Standards for Replacement, Repair and Maintenance of Overwater Structures, Including Moorage Facilities. The maintenance, repair and complete replacement of legally existing overwater structures is permitted; provided, that:
- i. All permit requirements of federal and state agencies are met;

### Plan set is in review by CORPS and WDFW

ii. The area, width, or length of the structure is not increased, but may be decreased;

#### The size of the structure will not increase.

iii. The height of any structure is not increased, but may be decreased; provided, that the height above the OHWM may be increased as provided in subsection (F)(2)(ix)(b) of this section;

### The height of the structure will not increase.

iv. The location of any structure is not changed unless the applicant demonstrates to the director's satisfaction that the proposed change in location results in: (A) a net gain in ecological function, and (B) a higher degree of conformity with the location standards for a new overwater structure;

#### The location of the structure will not change.

v. Piles shall not be treated with pentachlorophenol, creosote, CCA or comparably toxic compounds. If ammoniacal copper zinc arsenate (ACZA) pilings are proposed, the applicant shall meet all of the best management practices, including a post-treatment procedure, as outlined in the amended Best Management Practices of the Western Wood Preservers. All piling sizes are in nominal diameter; Any paint, stain or preservative applied to components PROJECT: Kittilsby, Lisa 2025 W. Mercer Way Mercer Island, WA 98040 COUNTY: KING COUNTY IN: LAKE WASHINGTON of the overwater structure must be leach resistant, completely dried or cured prior to installation. Materials shall not be treated with pentochlorophenol, creosote, CCA or comparably toxic compounds;

#### No piles will be treated with any toxic compounds.

vii. The applicant shall abide by the work windows for listed species established by the U.S. Army Corps of Engineers and Washington Fish and Wildlife;

#### The work shall be done within the work window.

viii. Disturbance of bank vegetation shall be limited to the minimum amount necessary to accomplish the project. Disturbed bank vegetation shall be replaced with native, locally adapted herbaceous and/or woody vegetation. Herbaceous plantings shall occur within 48 hours of the completion of construction. Woody vegetation components shall be planted in the fall or early winter, whichever occurs first. The applicant shall take appropriate measures to ensure revegetation success; Ch. 19.13 Shoreline Master Program | Mercer Island City Code Page 29 of 34 The Mercer Island City Code is current through Ordinance 20C-13, passed June 16, 2020.

#### No vegetation will be disturbed.

ix. Structural Repair. The structural repair, which may include replacement of framing elements, of moorage facilities that results in the repair of more than 50 percent of the structure's framing elements within a five-year period shall comply with subsections (F)(2)(ix)(a) through (F)(2)(ix)(c) of this section. For this section, framing elements include, but are not limited to, stringers, piles, pile caps, and attachment brackets, as shown in Figure D:

#### Repairing less than 50% - does not apply

a.One hundred percent of the decking area of the pier, dock, and any platform lifts must be fully grated with materials that allow a minimum of 40 percent light transmittance;

#### Repairing less than 50% - does not apply

b. The height above the OHWM for moorage facilities, except floats, shall be a minimum of one and one-half feet and a maximum of five feet; and

#### Repairing less than 50% - does not apply

c. An existing moorage facility that is five feet wide or more within 30 feet waterward from the OHWM shall be replaced or repaired with a moorage

#### Repairing less than 50% - does not apply

x. Exterior surface repair. The exterior surface repair, which may include the replacement of exterior surface materials of moorage facilities that results in the repair of more than 50 percent of the surface area of the moorage facility's decking, fascia, and platform lifts within a five-year period (see Figure D), shall be required to utilize materials that allow a minimum of 40 percent light transmittance over 100 percent of the dock; and

### Repairing less than 50% - does not apply

xi. Any decking that is removed in the course of repair shall be replaced with decking materials that allow a minimum of 40 percent light transmittance. Decking will be replaced with grated decking material that is 43% open space



Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119

Office: 206-236-1700 ext. 3 www.seabornpiledriving.com Scope of Work: We propose to repair (10) piles and repair the dock with grated decking material.

E o SHEI A9.


Adjacent Owners: KITILSBY TIM & LISA 2029 W MERCER WAY 98040

Datum: CORPS OF ENGINEERS 1919 SW Quarter Of Section 1, Township 24, Range 04

ast Updated: 4/8/2022 1:45 PM Dray-

APPLICANT:

# DETAILS - REPAIR



(S1) SLEEVE PILE REPAIR - TYP

(S2) DETAIL NOT IN USE

S3 DETAIL NOT IN USE

STEEL SLEEVE TABLE				
PILE Ø	MAX SPLICE HEIGHT	S1	S2	S3
9"	15"	6"	12"	3"
12"+	28"	6"	12"	3"

NOTES:

- ) MAX PILE LOAD = 1,200 # / PILE (BOAT LOAD PARALLEL TO DOCK).
- CONTACT ENGINEERING IF BOAT SIZE EXCEEDS GENERAL NOTES MAXIMUM ALLOWABLE.
  MINIMUM BOLT SPACING = 3"
- STRAP AXIS SHALL BE ORIENTED PERPENDICULAR TO LONGITUDINAL AXIS OF DOCK.

SECTION B'

STEEL PILE- TYP

WF PILE CAP

3/16 P

WF PILE CAP

3/16 P

WF PILE CAP

3/16 P

WF PILE TO MATCH

EXISTING WOOD Ø

SAWCUT TOP (E) PILE TO

PROVIDE SOLID BEARING

3/4" x 6" LAG

BENT PL \*\*x \*\* LENGTH AS

RECO TO MEET BOLT

SPACING DIMS.

CONTRACTOR TO VERIFY

SOLID JUNDAMAGED WOOD

TO REMAIN @ (E) PILE

CONTRACTOR TO VERIFY

SOLID JUNDAMAGED WOOD

TO REMAIN @ (E) PILE

S4 DETAIL NOT IN USE

Seaborn Pile Driving 1080 W Ewing St

Office: 206-236-1700 ext. 3 www.seabornpiledriving.com

Seattle, WA 98119

SPLICE PILE REPAIR - TYP

SEABORN . ESTD 1947 .

Scope of Work: We propose to repair (10) piles and repair the dock with grated decking material.

SHEET A10.0

Adjacent Owners: KITTILSBY TIM & LISA 2029 W MERCER WAY 98040

Datum: CORPS OF ENGINEERS 1919 SW Quarter Of Section 1, Township 24, Range 04

Seaborn Pile Driving Company 1080 W Ewing St Seattle, WA 98119


APPLICANT:

PROJECT: Kittilsby, Lisa 2025 W. Mercer Way Mercer Island, WA 98040 COUNTY: KING COUNTY IN: LAKE WASHINGTON

Last Updated: 12/22/2021 10:33

NWS-2021-76 PAGE 10 OF 12


# DETAILS - TRACK



3" LAG SCREW ANGLE BEHIND EVERY 2' 1/4" CARRIAGE BOLT SLEEPER TO ANGLE SLEEPER PER PLAN AT EACH END SIDE PLATE **DECKING PER PLAN** WF PILE CROWN -TYP LAG BOLT 3/4" x 6" LAG . 0 (2) <sup>3</sup>/<sub>4</sub>"Ø THRUBOLT **EPOXY COATED** SIDE PL <sup>1</sup>/<sub>2</sub>"x4"x32" - TYP EACH SIDE **EXISTING WOOD** PILE - TYP

S3) I-BEAM CAP TO WOOD PILE - TYP

DOCK SECTION w/PILES - TYP (s1)



PIN PILE @SHORE MOUNT - TYP S4 PIN PIL

EABORY

ESTD 1947

Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119

Office: 206-236-1700 ext. 3 www.seabornpiledriving.com

GLULAM EDGE BEAM (TYP) SLEEPER PER PLAN (TYP) 1/4"Ø CARRIAGE BOLT SLEEPER TO EA ANGLE DECKING TOP OF DECKING 5/8"Ø THRU-BOLT 2' O.C. @ PLATE **EPOXY COATED ANGLE** (2) 5/8"Ø THRU-BOLT EPOXY COATED, WF PER PLAN FLUSH WITH BEAM REF S3/SHEET12.0 3/16 V (TYP) S5 EDGE SECTION (STEEL TRACK) - TYP

SLEEPER, PER **CONT EPOXY** PLAN (TYP) COATED PL DECKING CL BOLTS GLULAM & BENT PL **EDGE BEAM** COUNTERSINK BOLT: 1" MAX EDGE BEAM PER PLAN  $\angle 7\frac{1}{2} \times 7\frac{1}{2} \times \frac{3}{8} \times 0' - 6"$ (DOES NOT CONTINUE w/(4) 3"Ø THRU-BOLT @ SIM CONDITION **EA LEG** S6 BEAM TO BEAM - TYP

Scope of Work: We propose to repair (10) piles and repair the dock with grated decking material.

HEET 11.0 SHE

Adjacent Owners: KITTILSBY TIM & LISA 2029 W MERCER WAY 98040

Datum: CORPS OF ENGINEERS 1919 SW Quarter Of Section 1, Township 24, Range 04

Last Updated: 12/22/2021 10:33 AM Dray

APPLICANT:

PROJECT: Kittilsby, Lisa 2025 W. Mercer Way Mercer Island, WA 98040 COUNTY: KING COUNTY IN: LAKE WASHINGTON

NWS-2021-XXX PAGE 11 OF 12

