



NAVD 88






SITE ADDITESS.
TAX PARCEL NUMBER:
NUMBER OF LOTS:
ZONING:
SITE AREA:
GROSS PROJECT AREA:
PROPOSED GROSS FLOOR A
PROPOSED ONSITE IMPERVIO
PROPOSED PERVIOUS AREA:
EXISTING LOT COVERAGE:
PROPOSED LOT COVERAGE:
PROPOSED BUILDING HEIGHT
NUMBER OF PARKING SPACE

- 1. (P) PLAT OF VITUS SCHMID'S EAST SEATTLE ACRE TRACTS, VOLUME 7 OF PLATS, PAGE 76
- 2. (P2) PLAT OF HILL HIGH ESTATES, VOLUME 68 OF PLATS, PAGE 28
- 3. (P3) PLAT OF DANIEL'S ADDITION, VOLUME 72 OF PLATS, PAGE 60

INTERSECTION OF 86TH AVENUE SE AND SE 47TH STREET. GNSS OBSERVATION OF MONUMENT

DRS DR. STRONG D.R. STRONG CONSULTING ENGINEERS ENGINEERS PLANNERS SURVEYORS 620 - 7th AVENUE KIRKLAND, WA 98033 0 425.827.3063 F 425.827.2423								
LORENZINI SP	TITLE SHEET	4719 86TH AVENUE SE MERCER ISLAND, WASHINGTON PARCEL NO. 7598100420						
TODD SHERMAN DESIGN BUILT HOMES		11400 SE 8TH STREET, SUITE 415 BELLEVUE, WASHINGTON 98004 206-909-8187						
	A START AND A STAR							
DATE REVISION APR 12.09.22 REVS. PER AGENCY COMMENTS MAJ								
DRAFTED DESIGNED PROJECT DATE: 1 PROJECT DRAWING: SHEET:	BY: JS ENGINEE 2.20.21 NO.: 2 C1	5E TR: MAJ 1071						




- FOUND COF	LEGEND:	
IN 4"X4" C Down 0.6'		FOUND SECTION CORNER AS NO
VISITED JUN		FOUND MONUMENT AS NOTED
	0	FOUND CORNER MONUMENT AS
		MAIL BOX
	Ē	POWER METER
	-@-	POWER POLE
		WATER METER
		ROCKERY
		STORM DRAIN CATCH BASIN
	63	SANITARY SEWER MANHOLE
	CV	GAS VALVE
	G	GAS METER
	VBF	VERTICAL BOARD FENCE
	0	DECIDUOUS TREE
	M.M.M.	EVERGREEN TREE
		SANITARY SEWER LINE
		STORM LINE
	OP	OVERHEAD POWER
	W	UNDERGROUND WATER
	G	UNDERGROUND GAS
		EDGE OF PAVEMENT
	XX	FENCE
CB TYPE RIM=318	Rock Constants States	CONCRETE

	NUMBER OF LOTS:	. 2
	LOT 1 AVERAGE SLOPE:	.7.5%
5	LOT 2 AVERAGE SLOPE:	8.5%
	PROPOSED STRUCTURE AREA:	TBD
	PROPOSED ONSITE IMPERVIOUS AREA:	11,029 S.F. (38.5%)
/	PROPOSED PERVIOUS AREA:	.17,615 S.F. (61.5%)
	EXISTING LOT COVERAGE:	.9,079 S.F. (31.7%)
	PROPOSED LOT COVERAGE:	10,826 S.F. (37.8%)
	PROPOSED BUILDING HEIGHT:	.TBD
	AVERAGE BUILDING ELEVATION:	. TBD
	EXISTING LANDSCAPING:	17,614 FT. (61.5%)
	PROPOSED LANDSCAPING:	17,615 S.F. (61.5%)
	NUMBER OF PARKING SPACES:	.4 MIN.

COPYRIGHT © 2023, D.R. STRONG CONSULTING ENGINEERS INC.


DRS D.R. STRONG CONSULTING ENGINEERS ENGINEERS PLANNERS SURVEYORS 620 - 7th AVENUE KIRKLAND, WA 98033 0 425.827.3063 F 425.827.2423							
LORENZINI SP	SITE PLAN 4719 86TH AVENUE SE MERCER ISLAND, WASHINGTON PARCEL NO. 7598100420						
TODD SHERMAN DESIGN BUILT HOMES	11400 SE 8TH STREET, SUITE 415 BELLEVUE, WASHINGTON 98004 206-909-8187						
	A STATE AND A STAT						
DATE REVISION APR 12.09.22 REVS. PER AGENCY COMMENTS MAJ							
PROJECT DATE: ;	BY: <b>JSE</b> ENGINEER: <b>MAJ</b> 1 <b>2.20.21</b> NO.: <b>21071</b>						

SHEET: 2 OF 4




											ropose Action						tree ''		ses	ses	
#	Tree Tag #	Species ID	DBH (in)	Adj. DBH (in)	Drip- line radius (ft)		OK in Grove	Health	Defects/Comments	Ret. Viable	Non-viable	Construct a	N	adius W	in fe	et S	Exceptional tree DBH > 24"	Value	Healthy Trees	Retained trees	
1	233	Douglas fir	21	21	18			ок	Typical of species	1			18	16	18	18		1	1	1	
2	234	Douglas fir	28	28	20			ок	Self-corrected lean towards west, dead wood, broken branches, dead twigs, typical of species	1			20	15	20	15	L	1	1	1	
3	235	Douglas fir	22	22	24			ок	Debris over crown, previous top loss, coning, dead wood, broken branches, typical of species			1	24	7	24	24		1	1		
1	236	Douglas fir	19	19	18			ок	Previous ivy @ root crown up to 50', typical of species, asymmetric canopy towards north			1	18	18	18	18		1	1		
5	237	Douglas fir	19	19	16			Fair	Self-corrected lean towards north, serpentine trunk, co- dominant leaders with included bark x2 @ 30' towards north, strong leader, reaction wood, horizontal crack @ 25', column of decay @ root crown up to 12' towards west, 3 calloused wounds towards west, free flowing sap		1		16	16	16	16		1			
6	238	Douglas fir	24	24	18		Y	Fair	Exposed roots, moss and lichen, previous top loss, dead wood, broken branches, elongated branches			1	18	18	18	18	L	1	1		
7	239	Bigleaf maple	38	38	38			Fair	Calloused wound @ 6' towards south, exposed roots, decay in roots towards north, dead wood, broken branches, grade lowered 3' towards east		1		38	38	38	38	Е	1			
в	241	Scots pine	13	13	14			ок	Typical of species	1			14	14	14	14		1	1	1	Γ
¢	242	Bigleaf maple	16	16	14			Fair	Vertical crack @ 3' up to 10' towards south, co-dominant leaders with included bark x3 @ 10'		1		14	14	14	14		1			
0	243	Bigleaf maple	10, 8, 14, 15	24	16			ОК	Co-dominant leaders with included bark x4 @ root crown, moss and lichen, typical of species			1	16	16	16	16	L	1	1		
1	244	White pine	15	15	8			ок	Serpentine trunk, dead wood, broken branches, typical of species			1	8	8	8	8		1	1		
2	245	White pine	19	19	10			ок	Dead wood, broken branches, a towards east, typical of species <b>Co-dominant leaders</b>			1	10	10	10	10		1	1		
3	246	Bigleaf maple	17, 18	25	22			ок	with included bark x2 @ 2', asymmetric canopy towards south, typical of species			1	22	22	22	22	L	1	1		
4	247	White pine	11	11	10			ок	Suppressed canopy, dead wood, broken branches, typical of species	1			10	10	6	6		1	1	1	
.5	248	Douglas fir	19	19	18			Fair	Epicormic branch formation @ 25' towards south, previous top loss, elongated branches, serpentine trunk, asymmetric canopy towards south		1		18	18	18	18		1			
16	249	Bigleaf maple	16, 44	47	30		Y	Fair	Co-dominant leaders with included bark x2 @ 4', exposed roots, calloused wound, dead wood, broken branches, asymmetric canopy towards north	1			30	30	21	30	E	1	1	1	
17	251	Bigleaf maple	26	26	28 north only			ок	Asymmetric canopy towards north, typical of species, dead wood, moss and lichen	1			28	28	28	28	L	1	1	1	
18	252	Douglas fir	28	28	18		Y	Fair	Self-corrected lean towards south, fill over crown, abnormal bark, popping bark, previous top loss, elongated branches, typical of species, dead wood, broken branches Dead wood, broken			1	18	18	18	18	L	1	1		
.9	253	Douglas fir	36	36	19			ок	branches, previous top loss, carpenter ants bark only	1			19	19	7	19	E	1	1	1	
0	254	Douglas fir	36, 28	45.5	16			ОК	Co-dominant leaders with included bark x2 @ 1', previous top loss @ 50', strong laterals, dead wood, broken branches, abnormal bark, popping bark, woodpecker activity	1			16	16	16	16	E	1	1	1	
1	255	Douglas fir	16	16	14		Y	Fair	Abnormal bark, shedding bark, popping bark, topped @ 50', strong lateral, low live crown ratio <10%	1			14	14	14	14		1	1	1	Ţ
2	256	Bigleaf maple	36, 24	43.5	26			Poor	Co-dominant leaders with included bark x2 @ 1', dead scaffolds, dead wood, cavity @ 3' towards north		1		26	26	26	26	E	1			
3	257	Incense cedar	8, 9	12	9			ок	Co-dominant leaders with included bark x2 @ 3',	1			9	9	9	9		1	1	1	ſ
	258	Incense	18	18	9			ок	typical of species Typical of species	1			9	9	9	9		1	1	1	+

ANY CONSTRUCTION WITHIN THE DRIPLINE OF A TREE TO BE RETAINED WILL REQUIRE AN AIR EXCAVATION ANALYSIS TO DETERMINE THAT THE TREE WILL NOT BE DAMAGED DURING CONSTRUCTION.



CONSUL ENGINEERS 620 - 7th AV	DRS D.R. STRONG CONSULTING ENGINEERS ENGINEERS PLANNERS SURVEYORS 620 - 7th AVENUE KIRKLAND, WA 98033 0 425.827.3063 F 425.827.2423									
LORENZINI SP	TREE PLAN 4719 86TH AVENUE SE MERCER ISLAND, WASHINGTON PARCEL NO. 7598100420									
TODD SHERMAN DESIGN BUILT HOMES	11400 SE 8TH STREET, SUITE 415 BELLEVUE, WASHINGTON 98004 206-909-8187									
	45232 CNAL DIAB23									
DATE REVISION APR 12.09.22 REVS. PER AGENCY COMMENTS MAJ 07.18.23 REVS. PER AGENCY COMMENTS MAJ										
DESIGNED PROJECT DATE: 1 PROJECT DRAWING:	NO.: <b>21071</b>									



	FOUND SECTION CORNER AS NOTED
	FOUND MONUMENT AS NOTED
Õ	FOUND CORNER MONUMENT AS NOT
$\boxtimes$	MAIL BOX
Ô	POWER METER
-©-	POWER POLE
	WATER METER
	ROCKERY
	STORM DRAIN CATCH BASIN
63	SANITARY SEWER MANHOLE
G∨ K	GAS VALVE
G	GAS METER
VBF	VERTICAL BOARD FENCE
• •	DECIDUOUS TREE
M. M	EVERGREEN TREE
	SANITARY SEWER LINE
	STORM LINE
OP	OVERHEAD POWER
W	UNDERGROUND WATER
G	UNDERGROUND GAS
	EDGE OF PAVEMENT
XX	FENCE
9 4 4 4 A A A	CONCRETE

<u>SITE VOL</u>	UME CAL	<u>CULA TIONS</u>	
CUT VOLUME (CU. YDS.)	FILL VOLUME (CU. YDS.)	NET VOLUME (CU. YDS.)	
535	766	231 FILL	
EXISTING GRADE AS SHO	WN.	PRESENT FINISH GRADE TO S STRUCTURAL EXCAVATION	-

R: \2021 \0 \21071 \3 \Drawings \Plo	ts PP 04-3	FG21071.c	dwg 7/18/2	2023 2:17:4	6 PN
COPYRIGHT ©	) 2023, D.R.	STRONG	CONSULTING	ENGINEERS	INC.

DRS DR. STRONG CONSULTING ENGINEERS ENGINEERS PLANNERS SURVEYORS 620 - 7th AVENUE KIRKLAND, WA 98033 0 425.827.3063 F 425.827.2423								
LORENZINI SP	CONCEPTUAL GRADING & UTILITY PLAN 4719 86TH AVENUE SE MERCER ISLAND, WASHINGTON PARCEL NO. 7598100420							
TODD SHERMAN DESIGN BUILT HOMES	11400 SE 8TH STREET, SUITE 415 BELLEVUE, WASHINGTON 98004 206-909-8187							
	AS232 AS232 DAL DAL DAL							
DATE REVISION APR 12.09.22 REVS. PER AGENCY COMMENTS MAJ 07.18.23 REVS. PER AGENCY COMMENTS MAJ								
PROJECT DATE: 1	BY: <b>JSE</b> ENGINEER: <b>MAJ</b> <b>2.20.21</b> NO.: <b>21071</b>							

SHEET: **4** OF **4**