Tree Report Document Summary - Note Ryan Ringe has contacted John Kenney and was given an extension to submit his final report later because of a Hospitalization of his child

Tree Info: Greif, 5236 W Mercer Way Mercer Island

Note: I have reviewed the final plans, and will be recommending the following information in my final report

There are 100 total trees in this inventory (59 *non-wetlands* subject property significant trees, 22 *wetlands* buffer subject property trees, 9 wetlands subject property trees, 7 adjacent property encroaching trees, and 3 ROW trees.)

A significant tree in Mercer Island is 6 in. DBH or greater for deciduous trees, and 6 ft. tall or greater for conifer trees.

General Notes

For all tree removals that are not in the development/disturbance zone, *I would recommend snagging them into wildlife trees instead of complete removal.* This will lessen the amount of wood removal, help with hillside erosion control, and provide wildlife habitat (and make the City happy).

- Trees #1444 and 1440 require their labels to be switched (1440 should be 1444 and vice versa).
- Tree # 1158 (20" Bigleaf Maple) is located in the 35 ft. Buffer zone, and is a hazard tree. It should be removed before construction begins (or after construction entrance roads are made; with all of the large tree removals, a roadway will need to be established before removal).
- Tree #1400 (10.5" Western Hemlock, Non-Wetlands tree) is in poor health and should be removed. It is also located within the proposed building footprint.
- Tree #1429 (16" Western Hemlock, Non-Wetlands tree) has decay in the upper stem, and is questionable. It should be removed unless specifically desired for retention, in which case it would require aerial inspection/ coring.
- Tree #1354 (47.3" Bigleaf Maple, Non-Wetlands tree) is a hazard tree and should be removed.
- Tree #1353 (34.7" Bigleaf Maple, Non-Wetlands tree) is a hazard tree and should be removed.
- Tree #1439 (41.1" Bigleaf Maple, Non-Wetlands tree) has a large dead stem that should be removed or shortened.
- Tree #1084 (29.5" Bigleaf Maple in the R.O.W.) is a hazard tree, and should be removed/ snagged into wildlife tree; if the City desires to retain it they should be aware of it and monitor frequently).

Trees Impacted by disturbance/ excavation to be Retained

Trees #1425, 1161, 1160, 1244, 1337, 1346, 04, A, B, C, D, and 1413 have disturbances within their driplines with additional protection notes; see below for notes and TPZ (Tree Protection Zone) radius.

Note: I have reviewed the final plans, and will be recommending the following information in my final report

There are 100 total trees in this inventory (59 *non-wetlands* subject property significant trees, 22 *wetlands buffer* subject property trees, 9 w*etlands* subject property trees, 7 adjacent property encroaching trees, and 3 ROW trees.)

A significant tree in Mercer Island is 6 in. DBH or greater for deciduous trees, and 6 ft. tall or greater for conifer trees.

General Notes

For all tree removals that are not in the development/ disturbance zone, *I would recommend snagging them into wildlife trees instead of complete removal*. This will lessen the amount of wood removal, help with hillside erosion control, and provide wildlife habitat (and make the City happy).

Trees #1444 and 1440 require their labels to be switched (1440 should be 1444 and vice versa).

Tree # 1158 (20" Bigleaf Maple) is located in the 35 ft. Buffer zone, and is a hazard tree. It should be removed before construction begins (or after construction entrance roads are made; with all of the large tree removals, a roadway will need to be established before removal).

Tree #1400 (10.5" Western Hemlock, Non-Wetlands tree) is in poor health and should be removed. It is also located within the proposed building footprint.

Tree #1429 (16" Western Hemlock, Non-Wetlands tree) has decay in the upper stem, and is questionable. It should be removed unless specifically desired for retention, in which case it would require aerial inspection/ coring.

Tree #1354 (47.3" Bigleaf Maple, Non-Wetlands tree) is a hazard tree and should be removed.

Tree #1353 (34.7" Bigleaf Maple, Non-Wetlands tree) is a hazard tree and should be removed.

Tree #1439 (41.1" Bigleaf Maple, Non-Wetlands tree) has a large dead stem that should be removed or shortened.

Tree #1084 (29.5" Bigleaf Maple in the R.O.W.) is a hazard tree, and should be removed/ snagged into wildlife tree; if the City desires to retain it they should be aware of it and monitor frequently).

Trees Impacted by disturbance/ excavation to be Retained

Trees #1425, 1161, 1160, 1244, 1337, 1346, 04, A, B, C, D, and 1413 have disturbances within their driplines with additional protection notes; see below for notes and TPZ (Tree Protection Zone) radius.

Subj	ect Property	Significant Trees						
Tree #	Species	Latin Name	DBH (in.)	Ht. (ft.)	Condition	Drip line Radius (ft.)	TPZ Radius (ft.)	Retain Yes/ No
(Non-	Wetlands)		·	·				•
1080	Bigleaf Maple	Acer macrophyllum	11.9	50	Good	18	N/A	No (Exc Fp)
1157	Bigleaf Maple	Acer macrophyllum	19.1	50	Fair	22	N/A	No (Exc Fp)
1245	Bigleaf Maple	Acer macrophyllum	47.3	90	Good/ Fair	32	N/A	No (Exc Fp)
1363	Bigleaf Maple	Acer macrophyllum	23.1	80	Good/ Fair	34	N/A	No (Exc Fp)
1365	Western Red Cedar	Thuja plicata	6.6	20	Good/ Fair	8	N/A	No (Exc Fp)
1364	Western Red Cedar	Thuja plicata	10.1	40	Good	17	N/A	No (Exc Fp)
1361	Douglas Fir	Pseudotsuga menziesii	20.7	70	Good/ Fair	23	N/A	No (Exc Fp)
1360	Bigleaf Maple	Acer macrophyllum	43.4	90	Good/ Fair	34	N/A	No (Exc Fp)
1359	Bigleaf Maple	Acer macrophyllum	12.8	70	Fair	17	N/A	No (Exc Fp)
1362	Bigleaf Maple	Acer macrophyllum	12.1	60	Good/ Fair	25	N/A	No (Exc Fp)
1400	Western Hemlock	Tsuga heterophylla	10.5	40	Poor	13	N/A	No (Condition)
1399	Western Hemlock	Tsuga heterophylla	10.0	40	Good/ Fair	13	N/A	No (Exc Fp)
1401	Bigleaf Maple	Acer macrophyllum	10.8	50	Good/ Fair	19	N/A	No (Exc Fp)
1402	Bigleaf Maple	Acer macrophyllum	37.4	75	Fair	30	N/A	No (Exc Fp)
1403	Bigleaf Maple	Acer macrophyllum	39.4	85	Good/ Fair	29	N/A	No (Exc Fp)
1404	Western Hemlock	Tsuga heterophylla	8.0	40	Good/ Fair	15	N/A	No (Exc Fp)
1405	Bigleaf Maple	Acer macrophyllum	23.3	80	Good/ Fair	30	N/A	No (Exc Fp)
1406	Bigleaf Maple	Acer macrophyllum	38.6	90	Good/ Fair	33	N/A	No (Impact)
1415	Bigleaf Maple	Acer macrophyllum	11.6	20	Fair/ Poor	12	N/A	No (Impact)

Tree #	Species	Latin Name	DBH (in.)	Ht. (ft.)	Condition	Drip line Radius (ft.)	TPZ Radius (ft.)	Retain Yes/ No
1414	Bigleaf Maple	Acer macrophyllum	28.9	90	Fair	30	N/A	No (Impact)
05	Bigleaf Maple	Acer macrophyllum	7.6	30	Good/ Fair	17	N/A	No (Exc Fp)
1429	Western Hemlock	Tsuga heterophylla	16.0	55	Fair/ Poor	16	N/A	No (Hazard)
1354	Bigleaf Maple	Acer macrophyllum	47.3	50	Poor	35	N/A	No (Hazard)
1353	Bigleaf Maple	Acer macrophyllum	34.7	75	Fair/ Poor	10/20	N/A	No (Hazard)
1426	Bigleaf Maple	Acer macrophyllum	48.9	90	Fair	32	N/A	No (Impact)
1425	Western Hemlock	Tsuga heterophylla	14.6	60	Fair	20	15	Yes
	Tree 1425 req ne radius of 20	uires a 15 ft. TPZ with ft.	no distu	ırbance; gı	rading shoul	d be limite	ed to 6 in.	within
1435	Bigleaf Maple	Acer macrophyllum	26.2	90	Good/ Fair	28	28	Yes
1437	Bigleaf Maple	Acer macrophyllum	34.7	90	Good	29	29	Yes
1438	Bigleaf Maple	Acer macrophyllum	28.5	90	Good/ Fair	31	31	Yes
1436	Bigleaf Maple	Acer macrophyllum	10.2	30	Good/ Fair	22	22	Yes
1439	Bigleaf Maple	Acer macrophyllum	41.1	90	Good/ Fair	32	32	Yes
1440	Bigleaf Maple	Acer macrophyllum	41.5	90	Good/ Fair	32	32	Yes
1444	Western Red Cedar	Thuja plicata	19.1	50	Good	18	18	Yes
06	Leyland Cypress	Cupressus × leylandii	4	15	Good/ Fair	7	N/A	No (Impact)
07	Leyland Cypress	Cupressus × leylandii	4	20	Good/ Fair	6	N/A	No (Impact)
08	Leyland Cypress	Cupressus × leylandii	4	20	Good/ Fair	7	N/A	No (Impact)
09	Leyland Cypress	Cupressus × leylandii	4.5	20	Good/ Fair	7	6	Yes
10	Leyland Cypress	Cupressus × leylandii	5	20	Good/ Fair	7	6	Yes

Tree #	Species	Latin Name	DBH (in.)	Ht. (ft.)	Condition	Drip line Radius (ft.)	TPZ Radius (ft.)	Retain Yes/ No
11	Leyland Cypress	Cupressus × leylandii	3.5	15	Good/ Fair	4	6	Yes
12	Leyland Cypress	Cupressus × leylandii	4	15	Good/ Fair	5	6	Yes
13	Leyland Cypress	Cupressus × leylandii	4.5	15	Good/ Fair	5	6	Yes
14	Leyland Cypress	Cupressus × leylandii	4	20	Good/ Fair	6	6	Yes
15	Leyland Cypress	Cupressus × leylandii	5.5	20	Good/ Fair	8	6	Yes
16	Leyland Cypress	Cupressus × leylandii	5	20	Good/ Fair	9	6	Yes
17	Leyland Cypress	Cupressus × leylandii	5	15	Good/ Fair	8	6	Yes
18	Leyland Cypress	Cupressus × leylandii	5	20	Good/ Fair	6	6	Yes
19	Leyland Cypress	Cupressus × leylandii	3.5	15	Good/ Fair	6	6	Yes
20	Leyland Cypress	Cupressus × leylandii	5	20	Good/ Fair	7	6	Yes
21	Leyland Cypress	Cupressus × leylandii	4.5	20	Good/ Fair	7	6	Yes
22	Leyland Cypress	Cupressus × leylandii	5	20	Good/ Fair	8	6	Yes
23	Leyland Cypress	Cupressus × leylandii	5	20	Good/ Fair	7	6	Yes
24	Leyland Cypress	Cupressus × leylandii	4.5	20	Good/ Fair	7	6	Yes
25	Leyland Cypress	Cupressus × leylandii	4	15	Good/ Fair	6	6	Yes
26	Leyland Cypress	Cupressus × leylandii	3.5	15	Good/ Fair	6	6	Yes
27	Leyland Cypress	Cupressus × leylandii	4.5	15	Good/ Fair	8	6	Yes
28	Western Red Cedar	Thuja plicata	5.2	25	Good/ Fair	12	N/A	No (Exc Fp)
29	Western Red Cedar	Thuja plicata	2.8	20	Good/ Fair	7	N/A	No (Exc Fp)
30	Western Red Cedar	Thuja plicata	1.9	15	Good/ Fair	7	N/A	No (Exc Fp)
31	Western Red Cedar	Thuja plicata	2.1	12	Good/ Fair	6	N/A	No (Exc Fp)

(35' V	Vetlands Buff	er)						
Tree #	Species	Latin Name	DBH (in.)	Ht. (ft.)	Condition	Drip line Radius (ft.)	TPZ Radius (ft.)	Retain Yes/ No
1081	Bigleaf Maple	Acer macrophyllum	21.7	60	Fair/ Poor	18	N/A	No (Impact)
1161	Bigleaf Maple	Acer macrophyllum	33.2	85	Good	30	20	Yes
	Tree 1161 rene radius of 3	quires a 20 ft. TPZ with 0 ft.	no distu	ırbance; g	rading shoul	d be limit	ed to 6 in.	within
1160	Bigleaf Maple	Acer macrophyllum	13.7	60	Good	26	14	Yes
	Tree 1160 rene radius of 2	quires a 14 ft. TPZ with 6 ft.	no distu	ırbance; g	rading shoul	d be limit	ed to 6 in.	within
1163	Bigleaf Maple	Acer macrophyllum	6.4	25	Fair/ Poor	14	7	Yes
	Tree 1163 re ne radius of 1	quires a 7 ft. TPZ with 4 ft.	no distui	rbance; gra	ading should	be limited	d to 6 in. v	within
1164	Bigleaf Maple	Acer macrophyllum	20.9	70	Good/ Fair	26	17	Yes
1158	Red Alder	Alnus rubra	20.0	25	Very Poor	21	N/A	No (hazard)
01	Bigleaf Maple	Acer macrophyllum	6.2	40	Good	18	N/A	No (Impact)
1156	Bigleaf Maple	Acer macrophyllum	23.1	70	Fair	22	N/A	No (Exc Fp)
1155	Bigleaf Maple	Acer macrophyllum	7.6	40	Fair	21	N/A	No (Exc Fp)
1246	Bigleaf Maple	Acer macrophyllum	9.0	50	Good/ Fair	20	N/A	No (Exc Fp)
1244	Red Alder	Alnus rubra	19.7	70	Good	16	15	Yes
	Tree 1244 rene radius of 1	quires a 15 ft. TPZ with 6 ft.	no distu	ırbance; g	rading shoul	d be limit	ed to 6 in.	within
1337	Red Alder	Alnus rubra	23.0	75	Good/ Fair	26	17	Yes
	Tree 1337 rene radius of 2	quires a 17 ft. TPZ with 6 ft.	no distu	ırbance; g	rading shoul	d be limit	ed to 6 in.	within
1367	Bigleaf Maple	Acer macrophyllum	10.1	55	Fair	21	N/A	No (Impact)

Tree #	Species	Latin Name	DBH (in.)	Ht. (ft.)	Condition	Drip line Radius (ft.)	TPZ Radius (ft.)	Retain Yes/ No
1358	Bigleaf Maple	Acer macrophyllum	36.8	100	Good/ Fair	36	N/A	No (Impact)
1357	Bigleaf Maple	Acer macrophyllum	18.4	70	Good/ Fair	30	N/A	No (Impact)
1345	Bigleaf Maple	Acer macrophyllum	44.3	100	Good/ Fair	39	N/A	No (Impact)
1346	Western Hemlock	Tsuga heterophylla	18.1	60	Good/ Fair	18	14	Yes
dripli	ne radius of 1							,
02	Bigleaf Maple	Acer macrophyllum	7.1	20	Fair	14	14	Yes
1356	Pacific Dogwood	Cornus nuttallii	10.6	40	Fair	19	N/A	No (Impact)
1351	Bigleaf Maple	Acer macrophyllum	9.3	40	Good/ Fair	22	N/A	No (Impact)
03	Bigleaf Maple	Acer macrophyllum	6.7	35	Good	16	16	Yes
1447	Bigleaf Maple	Acer macrophyllum	10.0	40	Good	17	17	Yes
(Wetl				I	1			
1241	Red Alder	Alnus rubra	20.5	60	Fair/ Poor	17	17	Yes
04	Bigleaf Maple	Acer macrophyllum	18.1	65	Good/ Fair	26	14	Yes
	Tree 04 requ ne radius of 2	ires a 14 ft. TPZ with n 6 ft.	o disturk	oance; gra	ding should l	e limited	to 6 in. w	ithin
1242	Red Alder	Alnus rubra	13.8	65	Fair/ Poor	11	11	Yes
1243	Western Hemlock	Tsuga heterophylla	15.7	70	Fair	11	11	Yes
1338	Red Alder	Alnus rubra	20.2	70	Good/ Fair	26	26	Yes
1339	Bigleaf Maple	Acer macrophyllum	12.0	65	Good/ Fair	22	22	Yes
1340	Red Alder	Alnus rubra	21.4	70	Fair	24	24	Yes
1341	Bigleaf Maple	Acer macrophyllum	13.0	60	Good/ Fair	22	22	Yes

Tree #	Species	Latin Name	DBH (in.)	Ht. (ft.)	Condition	Drip line Radius (ft.)	TPZ Radius (ft.)	Retain Yes/ No
1344	Red Alder	Alnus rubra	17.2	65	Good/ Fair	28	28	Yes
Encr	oaching Adja	acent Property Sign	ificant	Trees			•	1
A	Western Red Cedar	Thuja plicata	26	70	Good	20	20	Yes
	-	es a 20 ft. TPZ with no ot care/ pruning.	disturb	ance; Arbo	orist Supervi	sion durii	ng excavat	tion is
В	Western Hemlock	Tsuga heterophylla	22	80	Good/ Fair	26	22	Yes
	Tree B requir ne radius of 26	es a 22 ft. TPZ with no ft.	disturb	ance; grad	ing should b	e limited 1	to 6 in. wi	thin
C	Bigleaf Maple	Acer macrophyllum	16	50	Fair	24	12	Yes
	Tree C requir ne radius of 24	es a 12 ft. TPZ with no ft.	disturb	ance; grad	ling should b	e limited 1	to 6 in. wi	thin
D	Bigleaf Maple	Acer macrophyllum	17	70	Good/ Fair	24	13	Yes
	Tree D requir ne radius of 24	es a 13 ft. TPZ with no ft.	disturb	ance; grad	ling should b	e limited 1	to 6 in. wi	thin
E	Bigleaf Maple	Acer macrophyllum	40				30	Yes
1413	Bigleaf Maple	Acer macrophyllum	42	100	Good	34	21	Yes
	Tree 1413 req ne radius of 34	uires a 21 ft. TPZ with ft.	no distu	ırbance; g	rading shoul	d be limit	ed to 6 in.	within
1159	Red Alder	Alnus rubra	20				20	Yes
R.O.	W. Significar	nt Trees						
1079	Bigleaf Maple	Acer macrophyllum	20.1	60	Good/ Fair	36	N/A	No (Impact)
1082	Black Cottonwood	Populus trichocarpa	41.9	110	Good	29	N/A	No (Impact)
1084	Bigleaf Maple	Acer macrophyllum	29.5	70	Poor	25	N/A	No (hazard)