



Interlaken Engineering and Design, PLLC
7001 Seaview Ave NW, Suite 160-388,
Seattle, WA 98117 | (206) 470-9572

May 26, 2021

RE: 2012-199 Comment Response

Dear Ms. Kolke:

Please find responses to selected comments outlined below.

Comment responses are italicized.

Geotechnical:

Geotechnical special inspections should be itemized on the drawings and on the Mercer Island Cover Sheet. At a minimum, we anticipate the following: monitoring of erosion control, observation and monitoring of excavation, subsurface drainage installation, soil bearing verification, and structural fill verification and compaction.

Geotechnical Special Inspections as identified in the Response to Comments prepared by Earth Solutions NW LLC dated May 21, 2021 have been added to sheets C1 and C2.

Please feel free to reach out with any questions. Thank you.

Sincerely,

Matthew J. Haringa, P.E.

Principal

Interlaken Engineering and Design, PLLC