

EX. 1014

On Oct 26, 2012, at 6:48 AM, "Daniel Roupe" <danr@grp4.com> wrote:

<image001.gif>

Greg, we have an issue. I speaking with Doug last night about going out to take the photos today, he told me that they in fact did remove the ESM corner by the lake. I have no idea why they did it but they did. I am having it put back this morning in the same hole that it came out of. Needless to say I'm extremely upset about this. How do you want me to handle it as far as Lewis is concerned?

Daniel K. Roupe PLS

Daniel K Roupe PLS | President

Group Four, Inc

16030 Juanita-Woodinville Way NE, suite 200
Bothell, Washington 98011

Tel: 425.408.1152

Cell: 206.669.5501

Fax: 425.877.1341

Website: www.grp4.com