

February 12, 2019

Stuart Silk Architects  
2400 North 45<sup>th</sup> Street, Suite 200  
Seattle, Washington 98103

Attention: Eric Bredberg


Subject: Geologic Hazards Statement of Risk  
Perla Residence  
42xx Holly Lane  
Mercer Island, Washington

This letter constitutes our statement of risk regarding geologic hazards at the above referenced site per the City of Mercer Island Municipal Code (MIMC) Chapter 19.07.060.D2. This letter is based upon our previous work at the site as summarized in our letter reports dated July 20, 2016 and December 12, 2018 and review of the project plans prepared by Stuart Silk Architects dated December 12, 2018. None of the proposed construction will imping on or impact the steep slope area on the south and west sides of the lot except for the construction of a grasscrete drive at the top of the slope along the west side of the lot. Drainage from the grasscrete drive will be collected and tightlined to the site storm water collection system.

In our opinion, the proposed alteration associated with the grasscrete drive is so minor as not to pose a threat to public health, safety and welfare.

Please call if there are any questions.

Respectfully,



Robert M. Pride, PE, GE  
Principal Geotechnical Engineer