



# GEO Group Northwest, Inc.

Geotechnical Engineers, Geologists, &  
Environmental Scientists

13705 Bel-Red Rd  
Phone 425-649-8757

Bellevue, WA 98005  
Fax 425-649-8758

## DAILY FIELD REPORT

<b>Job #</b> G-4638	<b>Date</b> 10/6/2023	<b>Page #</b> 1 of 1	<b>Report #</b> 3
<b>Project Name &amp; Location</b> 4276 E Mercer Way, Mercer Island, WA			
<b>Permit #</b> 2103-055			

Per the request of the project ownership, a representative of GEO Group Northwest visited the site today to observe the installation of temporary erosion control.

### Temporary Erosion Control - Wet Weather Recommendations

We visited the site today to verify that erosion control BMPs have been properly implemented with regard to our Wet Season Grading letter (10-4-23). Today we observed that 1) a filter fabric fence has been installed at the south side of the disturbed soil areas thereby mitigating off-site sedimentation risk 2.) Plastic sheeting has been placed over the face of steep excavation slopes at the lower portion of the building pad and 3) straw has been placed at the gentle to moderate slopes at both the south side of the work area and at the lower portion of the access road, as recommended.

It is our opinion that the observed erosion control measures are appropriate for the anticipated wet weather conditions and subject to approval of the wet season waiver by Mercer Island, development may proceed per the approved plans and construction schedule noted in our 10-4-23 letter.

Per our letter we recommend that we return to check TESC conditions again in the event of forecasted or occurring heavy rainfall or erosion control concerns by others. TESC measures should be adequately maintained in order to remain effective.

Distribution: Millad Homes

Continued  
on next page