



Seaborn Pile Driving
1080 W Ewing St. Bldg B
Seattle WA 98119
seabornpiledriving.com

Review Response

Date: 06/14/23

Project Name: Seda Dock Repair

Response To: SHL23-015 and SEP23-004 SUB2 Review Letter; 5912 E Mercer Way, Mercer Island, WA 98040

Grace,

This letter is in response to the corrections for SHL23-015 and SEP23-004. Below are our responses to the questions/comments from 05/17/23.

1. Please revisit the surface coverage calculations and diagrams shown on sheet 14.0 of the plans:

a. Aerial imagery shows that there may be a shed located within 50 feet of the OHWM. Add this shed and any other hardscape onto the diagram and include in calculations if within 50 feet of the OHWM.

Please see the updated plan noting the updated square footage and hardscape calculations.

2. The current project narrative and scope of work does not include the removal of the existing boat lift with canopy and the new proposed platform lift. Please update the project narrative and scope of work.

Please see the updated plan set and other submittal documentation that contain an updated scope of work as the lift and canopy have been revised to be relocated.

Thank you for your time,

Dray Davick

Permit Technician

206-236-1700

permits@seabornpiledriving.com