



Seaborn Pile Driving
1080 W Ewing St. Bldg B
Seattle WA 98119
seabornpiledriving.com

Review Response

Date: 09/13/2023

Project Name: McMillan Dock Repair

Response To: SHL23-035 SUB2

To Tony Newton

This letter is in response to the corrections for SHL23-035. Below are our responses to the questions/comments from Sept 1st 2023.

1. All stringers will be replaced with steel frames, each steel frame will account for less than 50% of the linear footage of wood stringers to be replaced. (I.E. 994 lnft of wood stringer to be replaced with 414 lnft of steel frames) Noted on repair calculations.
2. Lift and Canopy to be removed.

Thank you for your time,

Zion Napier

Lead Permit Technician

206-236-1700

permits@seabornpiledriving.com