CITY OF MERCER ISLAND SHORT SUBDIVISION NO. SUB22-006

DECLARATION WE THE UNDERSIGNED, OWNER(S) IN FEE SIMPLE [AND CONTRACT PURCHASER(S)] OF THE LAND HEREIN DESCRIBED DO HEREBY MAKE A SHORT PLAT THEREOF PURSUANT TO RCW 58.17.060 AND DECLARE THIS SHORT PLAT TO BE THE GRAPHIC REPRESENTATION OF SAME, AND THAT SAID SHORT PLAT IS MADE WITH THE FREE CONSENT AND IN ACCORDANCE WITH THE DESIRE OF THE OWNER(S). IN WITNESS WHEREOF WE HAVE SET OUR HANDS AND SEALS PREMIUM HOMES OF MERCER ISLAND LLC, A WASHINGTON LIMITED LIABILITY COMPANY ACKNOWLEDGMENT STATE OF WASHINGTON SS. ON THIS DAY PERSONALLY APPEARED BEFORE ME ____ THAT EXECUTED THE WITHIN AND FOREGOING INSTRUMENT AND ACKNOWLEDGED SAID INSTRUMENT TO BE THE FREE AND VOLUNTARY ACT AND DEED OF SAID CORPORATION FOR THE PURPOSES THEREIN MENTIONED AND ON OATH STATED THAT THEY WERE AUTHORIZED TO EXECUTE SAID

CITY OF MERCER ISLAND APPROVALS

NOTARY PUBLIC

MY COMMISSION EXPIRES: __

RESIDING IN_

GIVEN UNDER MY HAND AND OFFICIAL SEAL THIS ____ DAY OF

EXAMINED AND APPROVED THIS	DAY OF	, 2023.
CODE OFFICIAL	-	
EXAMINED AND APPROVED THIS	DAY OF	, 2023.
CITY ENGINEER	-	

KING COUNTY DEPARTMENT OF ASSESSMENTS

EXAMINED AND APPROVED THIS	DAY OF, 2023.
ASSESSOR	DEPUTY ASSESSOR

ORIGINAL LEGAL DESCRIPTION

TRACTS 20 THROUGH 22, INCLUSIVE, IN BLOCK 4 OF FLOOD'S LAKE SIDE TRACTS DIVISION NO. 5, AS PER PLAT RECORDED IN VOLUME 34 OF PLATS, PAGE 6, RECORDS OF KING COUNTY, SITUATE IN THE COUNTY OF KING, STATE OF WASHINGTON.

REVISED LEGAL DESCRIPTION

COMMENCING AT THE NORTHWEST CORNER OF LOT 20, BLOCK 4 OF FLOOD'S LAKE SIDE TRACTS DIVISION NO. 5, AS PER PLAT RECORDED IN VOLUME 34 OF PLATS, PAGE 6, RECORDS

THENCE SOUTH 88'42'24" EAST ALONG THE NORTH LINE OF SAID LOT 20 105.58 FEET TO THE POINT OF BEGINNING:

THENCE CONTINUING SOUTH 88'42'24" EAST ALONG SAID NORTH LINE 124.42 FEET TO THE NORTHEAST CORNER OF SAID LOT 20:

THENCE SOUTH 01'27'06" WEST ALONG THE EAST LINE OF LOTS 20 AND 21 OF SAID BLOCK 4 A DISTANCE OF 78.33 FEET;

THENCE SOUTH 25'00'36" WEST ALONG THE EAST LINE OF SAID LOT 21 A DISTANCE OF 40.05 FEET TO A POINT ON A LINE PARALLEL WITH AND 65.00 FEET NORTH OF THE SOUTH LINE OF LOT 22 OF SAID BLOCK 4;

THENCE ALONG SAID PARALLEL LINE NORTH 88'42'24" WEST 108.09 FEET: THENCE NORTH 0117'36 EAST 115.00 FEET TO THE POINT OF BEGINNING.

SITUATE IN THE CITY OF MERCER ISLAND, COUNTY OF KING, STATE OF WASHINGTON.

BEGINNING AT THE NORTHWEST CORNER OF LOT 20, BLOCK 4 OF FLOOD'S LAKE SIDE TRACTS DIVISION NO. 5, AS PER PLAT RECORDED IN VOLUME 34 OF PLATS, PAGE 6, RECORDS OF

THENCE SOUTH 88'42'24" EAST ALONG THE NORTH LINE OF SAID LOT 20 105.58 FEET; THENCE SOUTH 01'17'36" WEST 115.00 FEET TO A POINT ON A LINE PARALLEL WITH AND 65.00 FEET NORTH OF THE SOUTH LINE OF LOT 22 OF SAID BLOCK 4; THENCE ALONG SAID PARALLEL LINE NORTH 88'42'24" WEST 105.90 FEET TO A POINT ON THE

WEST LINE OF LOT 21 OF SAID BLOCK 4; THENCE NORTH 01'27'06" EAST ALONG THE WEST LINE OF SAID LOT 20 AND 21 115.00 FEET TO THE POINT OF BEGINNING.

SITUATE IN THE CITY OF MERCER ISLAND, COUNTY OF KING, STATE OF WASHINGTON.

COMMENCING AT THE NORTHWEST CORNER OF LOT 20, BLOCK 4 OF FLOOD'S LAKE SIDE TRACTS DIVISION NO. 5, AS PER PLAT RECORDED IN VOLUME 34 OF PLATS, PAGE 6, RECORDS

THENCE SOUTH 01'27'06" WEST ALONG THE WEST LINE OF LOTS 20 AND 21 OF SAID BLOCK 4 A DISTANCE OF 115.00 FEET TO THE POINT OF BEGINNING;

THENCE CONTINUING SOUTH 01'27'06" WEST ALONG THE WEST LINE OF LOTS 21 AND 22 OF SAID BLOCK 4 A DISTANCE OF 65.00 FEET TO THE SOUTHWEST CORNER OF SAID LOT 22; THENCE SOUTH 88'42'24" EAST ALONG THE SOUTH LINE OF SAID LOT 22 A DISTANCE OF 185.62 FEET TO THE SOUTHEAST CORNER OF SAID LOT 22; THENCE NORTH 25'00'36" EAST ALONG THE EAST LINES OF SAID LOTS 21 AND 22 A


DISTANCE OF 71.00 FEET TO A POINT ON A LINE PARALLEL WITH AND 65.00 FEET NORTH OF THE SOUTH LINE OF LOT 22 OF SAID BLOCK 4;

THENCE ALONG SAID PARALLEL LINE NORTH 88'42'24" WEST 213.99 FEET TO THE POINT OF

SITUATE IN THE CITY OF MERCER ISLAND, COUNTY OF KING, STATE OF WASHINGTON.

SHORT PLAT NOTES


ALL BUILDING PERMITS ARE SUBJECT TO MEETING CURRENT FIRE CODE REQUIREMENTS AT THE TIME OF A COMPLETE SUBMITTAL, INCLUDING FIRE APPARATUS ACCESS AS OUTLINED IN ADOPTED CODE SECTIONS OF THE INTERNATIONAL FIRE CODE APPENDIX D. FIRE PLAN REVIEWS WILL BE CONDUCTED AT TIME OF BUILDING PERMIT SUBMITTAL AND MAY REQUIRE ADDITIONAL FIRE PROTECTION SYSTEMS AND/OR ADDITIONAL FIRE PREVENTION MEASURES FOR BUILDING APPROVAL.




VICINITY MAP N.T.S.

SURVEYOR'S NOTES

- 1. THIS SURVEY WAS MADE BY FIELD TRAVERSE USING A LEICA 1203 3" ROBOTIC TOTAL STATION AND TOPCON HIPER SR GPS WITH RESULTING CLOSURES EXCEEDING THE MINIMUM ACCURACY STANDARDS AS SET FORTH BY WAC 332-130.
- 2. THE BOUNDARY CORNERS AND LINES DEPICTED ON THIS MAP REPRESENT DEED LINES ONLY. THEY DO NOT PURPORT TO SHOW OWNERSHIP LINES THAT MAY OTHERWISE BE DETERMINED BY A COURT OF LAW.
- 3. THE TITLE REPORT WAS PROVIDED BY OLD REPUBLIC NATIONAL TITLE INSURANCE COMPANY, FILE NO. A46014-SGW-217187, DATED APRIL 19, 2021 AT 8:00 AM.
- 4. ANY UTILITIES SHOWN TO BE FIELD VERIFIED BEFORE PLANNING OR CONSTRUCTION.
- 5. FIELD WORK FOR THIS PROJECT WAS PERFORMED ON JULY, 2019 AND IS THEREFORE A REFLECTION OF THE CONDITIONS AT THAT TIME. ALL MONUMENTS WERE VISITED OR SET ON JULY, 2019. THIS SITE CONTAINS IMPROVEMENTS NOT LOCATED OR SHOWN AS A
- 6. THIS SURVEY COMPLIES WITH ALL STANDARDS AND GUIDELINES OF THE "SURVEY RECORDING ACT," CHAPTER 58.09 RCW AND 332-130 WAC.





LAND SURVEYING • MAPPING • CONSTRUCTION LAYOUT

RECORDER'S CERTIFICATE FILED FOR RECORD THIS_____, 20____, 20____ _ IN BOOK__

____OF _____SURVEYS, AT PAGE_

AT THE REQUEST OF PREMIUM HOMES OF MERCER ISLAND, LLC

MANAGER SUPERINTENDENT OF RECORDS


SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE SURVEY RECORDING ACT AT THE REQUEST OF

PREMIUM HOMES OF MERCER ISLAND, LLC

IN 5/5/2023,


CERTIFICATE NO. 44651, EVAN M. WAHLSTROM EXP 10/4/24




PREMIUM HOMES OF MERCER ISLAND. LLC P.O. BOX 1639 MERCER ISLAND, WA 98040

SITE ADDRESS: 7216 93RD AVE SE MERCER ISLAND, WA KING COUNTY TAX PARCEL NO. 2581900210 SURVEY IN: NW 1/4, SE 1/4, SEC. 30, T.24N, R.5E, W.M.

DRAFTED: AG	DATE: 5/5/2023	JOB NO.: BARCE-190624
CHECKED: EMW	SCALE: N/A	SHEET 1 OF 2



PRELIMINARY SHORT PLAT APPLICATION **7216 93**RD **AVE SE** MERCER ISLAND, WA 98040



PROPERTY INFORMATION:

REMOVE EXISTING SINGLE FAMILY HOME ON 39,145 S.F. LOT IN THE R-8.4 ZONE. THE ADJACENT PROPERTY TO THE SOUTHEAST IS R-9.6, WHILE ALL OTHER ADJACENT PROPERTIES

PROPOSE 3 LOT SHORT PLAT TO ULTIMATELY BUILD A DETACHED SINGLE FAMILY HOME ON EACH LOT. EACH LOT WILL TAKE ACCESS FROM 93RD AVENUE WITH A COMMON ACCESS EASEMENT FOR LOTS 1 & 2. A COMMON UTILITY EASEMENT FOR ALL THREE LOTS WILL BE IN THE SAME LOCATION. EACH LOT IS OVER 9,000 S.F.

STEEP SLOPES HAVE BEEN IDENTIFIED ON THE EAST SIDE OF THE PROPERTY. A MEMORANDUM HAS BEEN ISSUED TO THE CITY DETERMINING THE ONSITE RAVINE DOES NOT MEET THE CITY'S DEFINITION OF A WATERCOURSE AND IS THEREFORE NOT REGULATED.

7216 93RD AVE SE

5, AS PER PLAT RECORDED IN VOLUME 34 OF PLATS, PAGE 6, RECORDS OF KING COUNTY,

QUARTER-SECTION-TOWNSHIP-RANGE:

SE-30-24-5

39,144 S.F.

A1.1 TREE REMOVAL, RETENTION & PLANTING PLAN

CONTACT INFORMATION:

MERCER ISLAND WA 98040 206-724-1072

CIVIL ENGINEER: G2 CIVIL

1700 NW GILMAN BLVD, SUITE 200 ISSAQUAH, WA 98027 CONTACT: LAUREN ELLIOTT

206-443-1181 CONTACT: MATT GLASER

ARBORIST: LAYTON TREE CONSULTING, LLC PO BOX 572 SNOHOMISH, WA 98291-0572 425-220-5711

CONTACT: BOB LAYTON

<u>GEOTECH:</u> ROBERT M. PRIDE, LLC 13203 HOLMES POINT DRIVE NE KIRKLAND, WA 98034 CONTACT: BOB PRIDE RMPGEO@AOL.COM

SURVEYOR: INFORMED LAND SURVEY P.O. BOX 5137 TACOMA, WA 98415 253-678-2539 CONTACT: EVAN WAHLSTROM

9505 19TH AVENUE SE, SUITE 106



SITE ADDRESS:

MERCER ISLAND, WA, 98040

TRACTS 20 THROUGH 22, INCLUSIVE, IN BLOCK 4 OF FLOOD'S LAKE SIDE TRACTS DIVISION NO. SITUATE IN THE COUNTY OF KING, STATE OF WASHINGTON.

TAX PARCEL # 258190-0210

GROSS SITE AREA:

DRAWING INDEX:

A0 COVER SHEET

1 OF 1 TOPOGRAPHIC SURVEY

1 OF 2 CIVIL SITE PLAN

2 OF 2 PROFILES

A1.2 EXCEPTIONAL TREE PLAN

OWNER: BARCELO HOMES PO BOX 1639

CONTACT: BOGDAN MAKSIMCHUK BOGDAN@BARCELOHOMES.COM

425-364-5286

LAURENE@G2CIVIL.COM

ARCHITECT:
MCCULLOUGH ARCHITECTS 2910 FIRST AVE. SOUTH, SUITE 201 SEATTLE, WA 98134


MATT@MCCULLOUGHARCHITECTS.COM


EWAHLSTROM@I-LANDSURVEY.COM WETLAND CONSULTANT: WETLAND RESOURCES, INC.

EVERETT, WA 98208 425-337-3174 CONTACT: NIELS PEDERSEN, PWS SHOR


U

Cover Sheet





Tree Removal Retention & Planting Plan



#1 REMOVE

#6 REMOVE

#27* RETAIN

#29 RETAIN

#35* RETAIN


#104 RETAIN

#106 RETAIN

U !

APPLICATION

Exceptional






NOTES	SUBMITTED TO CLIENT	REVISED PER CITY COMMENTS				
DATE	3-30-21	5-25-21	04-28-22	08-02-22	2-16-23	
СНКО ВҮ	KAL	KAL	NEM	NEM	EDM	
DWN BY	KAL	KAL	TAU	TLK	TLK	


1700 NW GILMAN B ISSAQUAH, WA 980 PHONE: (425) 821-5


ARY CIVIL SITE PLAN PLAT - 93RD AVE SE SUB22-006 HOMES OF MERCER ISLAND LLC PO BOX 1639

SHORT PLAT - SUB2
SUB2
PREMIUM HOMES OF

SHEET **1** of **2**







CALL 3 WORKING DAYS BEFORE YOU DIG

811

UTILITIES UNDERGROUND LOCATION
CENTER
(ID,MT,ND,OR,WA)

ELECTRIC - RED SEWER - GREEN GASIOIL - YELLOW
SURVEY - PINK TELICATY - ORANGE
PROPOSED - WHITE WATER - BLUE

APPROVED:

CITY OF MERCER ISLAND DEVELOPMENT SERVICES GROUP


D


SUBMITTED TO CLIENT
REVISED PER CITY COMMENTS
REVISED PER CITY COMMENTS
REVISED PER CITY COMMENTS
REVISED PER CITY COMMENTS

1700 NW GILMAN BLVD, STE 200 ISSAQUAH, WA 98027 PHONE: (425) 821-5038

PRELIMINARY CIVIL SITE PLAN
SHORT PLAT - 93RD AVE SE
SUB22-006
PREMIUM HOMES OF MERCER ISLAND LLC

SHEET 2 of 2





NOTES	SUBMITTED TO CLIENT	REVISED PER CITY COMMENTS				
DATE	3-30-21	5-25-21	04-28-22	08-02-22	2-16-23	
снкр ву	KAL	KAL	NEM	NEM	EDM	
AB NMO	KAL	KAL	JAT	TLK	TLK	

1700 NW GILMAN E ISSAQUAH, WA 980 PHONE: (425) 821-

INAKY CIVIL SITE FLAN

PLAT - 93RD AVE SE

SUB22-006

IM HOMES OF MERCER ISLAND LLC

PO BOX 1639

MERCER ISLAND LLC

MERCER ISLAND LLC

PRELIMINAF SHORT PL

SHEET **1** of **2**



Layton Tree Consulting LLC


Tree/ Tag #		Species Scientific Name	DBH (inches)	Height (feet)	Drip-Liı		ts of Distu	ırbance	Condition	Exceptional Yes/No	l Comments	Proposal
<u> </u>				, , ,	N	S	E	W				
1	bigleaf maple	Acer macrophyllum	32	96	30	10	22	18	Fair	Yes	asymmetric crown to north, deadwood	Remove
2	bigleaf maple	Acer macrophyllum	26	98	12	14	10	18	Fair	No	forked top, moderate included bark	Remove
3	bigleaf maple	Acer macrophyllum	11	75	18	0	16	0	Fair	No	asymmetric crown to NE, suppressed	Remove
4	bigleaf maple	Acer macrophyllum	24	105	0	22	20	6	Fair	No	asymmetric crown to southeast	Remove
5	bigleaf maple	Acer macrophyllum	22	32	Х	Х	Х	Х	Poor	No	broken, 90% dead	Remove
6	bigleaf maple	Acer macrophyllum	37	108	24	8	8	34	Fair	Yes	trunk forks at 8 feet, codominant stems	Remove
7	bigleaf maple	Acer macrophyllum	18	105	8	12	5	16	Fair	No	leans west, decent vigor	Remove
8	bigleaf maple	Acer macrophyllum	14	98	11	6	6	9	Fair	No	poor trunk taper	Remove
9	bigleaf maple	Acer macrophyllum	18	102	11	6	14	5	Fair	No	poor trunk taper, forked top	Remove
10	bigleaf maple	Acer macrophyllum	23	116	6	28	16	12	Fair	No	natural lean south, forked top, deadwood	Remove
11	bigleaf maple	Acer macrophyllum	22	102	10	6	14	17	Fair	No	natural lean west	Remove
12	Western red cedar	Thuja plicata	26	64	14	13	13	16	Fair	No	sparse top foliage, suppressed by #11	Remove
13	bigleaf maple	Acer macrophyllum	19,15,9 (26)	95	9	20	18	12	Fair-poor	No	moderate trunk decay, crown dieback	Remove
14	bigleaf maple	Acer macrophyllum	20	86	9	12	0	28	Fair	No	natural lean west, forked top	Remove
15	bigleaf maple	Acer macrophyllum	18	85	8	14	16	15	Fair	No	forked top, compact crown	Remove
16	bigleaf maple	Acer macrophyllum	22	80	5	18	20	10	Fair-poor	No	significant crown dieback	Remove
17	bigleaf maple	Acer macrophyllum	14	86	6	8	14	6	Fair	No	compact crown	Remove
18	bigleaf maple	Acer macrophyllum	26	95	16/16	24	5	22/16	Fair	No	forked top, moderate included bark	Save
19	bigleaf maple	Acer macrophyllum	25	97	16	22	18	5	Fair	No	forked top, moderate included bark	Save
20	bigleaf maple	Acer macrophyllum	28	94	8	18	12	14	Fair	No	typical	Save
21	bigleaf maple	Acer macrophyllum	27	98	14	5	14	10	Fair	No	trunk seam, moderate deadwood	Save
22	bigleaf maple	Acer macrophyllum	25	94	18	4	0	22	Fair	No	natural lean west, asymmetric crown	Save
23	bigleaf maple	Acer macrophyllum	22	96	26	0	0	16	Fair	No	natural lean northwest	Save
24	bigleaf maple	Acer macrophyllum	24	84	35	0	0	0	Fair-poor	No	trunk decay, heavy lean north	Save
25	bigleaf maple	Acer macrophyllum	25	83	Х	Х	Х	Х	Poor	No	extensive trunk decay, leans north	Save
26	bigleaf maple	Acer macrophyllum	16,12 (20)	82	34	18	14	12	Fair	No	moderate trunk decay, moderate deadwood	Save
27	bigleaf maple	Acer macrophyllum	37	88	22	16	18	16	Fair-poor	*No	large trunk cavity, trunk split, decent vigor	Save
28	bigleaf maple	Acer macrophyllum	18	86	0	20	6	16	Fair	No	significant natural lean south	Save
29	bigleaf maple	Acer macrophyllum	34	94	26	8	20	10	Fair	Yes	natural lean north	Save
30	bigleaf maple	Acer macrophyllum	26,20 (33)	92	6	26	16	13	Fair-poor	No	significant trunk decay, natural lean south	Save
31	bigleaf maple	Acer macrophyllum	13	38	10	14	15	0	Fair	No	topped in past, low risk	Save
32	bigleaf maple	Acer macrophyllum	8,7 (11)	34	14	4	16	4	Fair	No	suppressed, natural lean north	Save
33	bigleaf maple	Acer macrophyllum	15	32	X	Х	Х	Х	Poor	No	broken, extensive decay	Save
34	bigleaf maple	Acer macrophyllum	13	34	12	8	10	10	Fair	No	broken, failed top, decent vigor, low risk	Save
35	bigleaf maple	Acer macrophyllum	40,34 (52)	78	28/20	12	22	18/20	Fair-poor	*No	extensive basal rot, broken top	Save
36	bigleaf maple	Acer macrophyllum	14	71	18/12	0	8	6	Fair	No	natural lean north	Save
37	bigleaf maple	Acer macrophyllum	8,8 (11)	58	16/10	10	16	8	Fair	No	natural lean north	Save
38	Western red cedar	Thuja plicata	15	49	12	12	11	12/12	Good	No	full crown, good vigor	Save
39	Douglas fir	Pseudotsuga menziesii	10	61	8	7	8	8/8	Fair-good		somewhat suppressed by maple	Save
40	bigleaf maple	Acer macrophyllum	11,9 (14)	47	13	13	15	6	Fair	No	fork at base, decent vigor	Remove
41	bigleaf maple	Acer macrophyllum	9,8,5 (13)	42	14	12	6	12/12	Fair	No	tight cluster, typical	Save
	bigleaf maple	Acer macrophyllum	32	74	27/16	10	32/16	12/16	Fair	No	leans northeast, end weight prune	Save
		Prunus americana cv	9,8 (12)	21	14	7	9	12/10	Fair-poor	No	topped, not maintained	Save
	boring Trees			<u> </u>		└	<u> </u>	<u> </u>	<u> </u>	<u> </u>		
	bigleaf maple	Acer macrophyllum	20	56	NA	NA	NA	6/6	Fair	No	multiple tops , approx 10 feet off pl	Protect
	Douglas fir	Pseudotsuga menziesii	24	86	NA	NA	NA	5/5	Good	No	approx 10 feet off pl , old broken top	Protect
	bigleaf maple	Acer macrophyllum	19,18	42	NA	NA	NA	10/5	Poor	No	approx 5 feet off pl, broken top	Protect
	bigleaf maple	Acer macrophyllum	46	103	NA	20/20	NA	32/20	Good	Yes	sound, good form	Protect
		Betula pendula	18	78	NA	10/10	10	12	Fair	No	incipient top decline	Protect
		Acer palmatum	14,10	36	NA	16/10	17	16	Good	Yes	no concerns	Protect
	English holly	llex aquifolium	8,7,6	20	NA	6/4	8	8/6	Fair	No	typical	Protect
	Austrian pine	Pinus nigra	18	53	10	12	8	NA	Good	No	above keystone retaining wall	Protect
	Douglas fir	Pseudotsuga menziesii	30	104	10	14	14	NA	Good	Yes	appears sound, good vigor	Protect
	Douglas fir	Pseudotsuga menziesii	45	120	16	14	NA	10	Good	Yes	appears sound, good vigor	Protect
	red alder	Alnus rubra	12,13	70	14	12	12	NA	Fair	No	decent vigor	Protect
	bigleaf maple	Acer macrophyllum	26	66	18	22	20	NA	Good	No	decent form, approx. 12-feet to retaining wall	Protect
	bigleaf maple	Acer macrophyllum	14,8	60	8	12	8	NA	Fair	No	a few feet above rockery, decent form	Protect
	bigleaf maple	Acer macrophyllum	9,8,7	64	10	8	13	NA	Fair	No	at edge of rockery, typical	Protect
115	bigleaf maple	Acer macrophyllum	12,10,7	76	10	12	18	NA	Fair	No	a few feet off driveway edge	Protect
		<u> </u>		·		↓ '	 /	 '				
	1	,	1		,	1	,	1	,			

*-meets exceptional size threshold but is in poor condition
Drip-Line and Limits of Disturbance measurements from face of trunk
Drip-Line and Limits of Disturbance measurements for Neighboring trees from fence/property line
Calculated DBH: the DBH is parenthesis is the square root of the sum of the dbh for each individual stem squared (example with 3 stems:
dbh = square root [(stem1)2 +(stem2)2 +(stem3)2]).

TREE REPLACEMENT CALCULATION

	Tree Dia.	Exceptional (Yes,	Replacement Trees
Tree #	(in)	No, Grove)	Required
1	32	YES	6
2	26	NO	3
3	11	NO	2
4	24	NO	3
5	22	DEAD	0
6	37	YES	6
7	18	GROVE	6
8	14	GROVE	6
9	18	GROVE	6
10	23	GROVE	6
11	22	GROVE	6
13	26	GROVE (POOR)	4
14	20	GROVE	6
15	18	GROVE	6
16	22	GROVE (POOR)	3
17	14	GROVE	6
40	14	NO	6
		Total Replacement	81

REFER TO REPLANTING PLAN PREPARED FOR OTHERS FOR LOCATIONS OF REPLACEMENT TREES



CITY OF MERCER ISLAND DEVELOPMENT SERVICES GROUP Date



	KAL	KAL	3-30-21	3-30-21 SUBMITTED TO CLIENT
, STE 200	KAL	KAL	5-25-21	5-25-21 REVISED PER CITY COMMENTS
	JAT	NEM	04-28-22	04-28-22 REVISED PER CITY COMMENTS
	TLK	NEM	08-02-22	08-02-22 REVISED PER CITY COMMENTS
	TLK	EDM	2-16-23	2-16-23 REVISED PER CITY COMMENTS

SHEET **2** of **2**