

Re: City Plan Review Comments for Building Code Conformance - Permit 2012-199 Merlino Residence

6 messages

Dan Brobst <dan@brobstdesignworks.com>

Thu, Jun 3, 2021 at 2:33 PM

To: Jcmerlino <JCMerlino@comcast.net>, "rbe1992 (rbe1992@gmail.com)" <rbe1992@gmail.com> Co: John Merlino <john.merlino@centurycommunities.com>

Ross - this is the hot one for the Merlino's that I told you about on the phone. I bubbled the added structure under the bearing wall that is the wall between the laundry and mudroom, up the master door. I also added the blocking under the perpendicular shear wall and called out detail L. Don Cole also had a comment about the Kzt value, item 1. Can you jump on this one?

Thank you!

These are the comments from Don Cole.

PEPUS.

Page 2 comment - Don Cole

 Provide calculations and supporting documentation from the structural engineer to justify the Kzt of 1.3 used within the lateral calculations. Note the city wind map indicates Kzt of 1.6 in this area. Note

 No justification is needed if Kzt 1.6 or greater is utilized.

PLEASE SEE CALCS W/ KZ = 1.6 PREVIDED, NO CHAPGE Page 7 comment - Don Cole SON AS QUALCE GOVERNS.

1. Provide calculations and supporting documentation from the structural engineer to justify the Kzt of 1.3 used within the lateral calculations. Note the city wind map indicates Kzt of 1.6 in this area. Note - No justification is needed if Kzt 1.6 or greater is utilized.

2. Show blocking between joists beneath bearing wall above and provide calculations to show adequacy of joists to support tributary roof, wall, upper floor and lower floor loads.

THANKS FOR THE CORRECTION, PLEASE SEE
CALCS PREVIOED

THANKS MR. DON.

Merlino for RB check 6-3-2021.pdf 2467K

2055,

6/9/21

RB Engineers <rbe1992@gmail.com>

To: Dan Brobst <dan@brobstdesignworks.com>

Cc: Jcmerlino <JCMerlino@comcast.net>, John Merlino <john.merlino@centurycommunities.com>

Thu, Jun 3, 2021 at 4:01 PM

Mr. Dan I need the detail s and notes also, please [Quoted text hidden]