



5401 W. Mercer Way

Location	Inspector
5401 W. Mercer Way Mercer Island	ToddVecchio Todd@SoundSewerinspection.com 206-619-9990



2/21/2021

Purpose:

To video inspect the subject's lateral sewer line; Video of the sewer inspection is ready at: https://youtube.com/watch?v=_Wwfgtgq2Y

Quote:

\$275 for the sewer inspection; An online invoice powered by PayPal was sent to the client.

Recommended Action:

The line needs to be cleaned/jetted to remove the debris and roots from the line

2/19/2021 10:47:13 AM

11' 7"

Access to the sewer line is located in the crawl space



2/19/2021 10:46:04 AM

53' 0"

Debris in the line



2/19/2021 10:45:50 AM

57' 2"

Video: <https://youtube.com/watch?v=BNsjsSvxgEQ>

2/19/2021 10:45:42 AM

57' 6"

Sewer line located under the patio on the south side of the house; approx. 3' feet deep. Area marked with green flag.



2/19/2021 10:37:40 AM

59' 0"

Video: https://youtube.com/watch?v=_Wwfagtq2Y



2/19/2021 10:41:27 AM


89' 9"

Original concrete piped sewer line

2/19/2021 10:40:34 AM

100' 1"


Root intrusion



2/19/2021 10:40:58 AM

100' 1"

Connection into the main city line on the south side of the property



2/19/2021 10:39:39 AM

109' 3"