SE 1/4, SE 1/4, SECTION 13, TOWNSHIP 24 NORTH, RANGE 4 EAST, W.M.

SURVEYOR'S NARRATIVE;

NORTH LINE NOT DEED.

REFERENCE SURVEYS:

LEGEND

FOUND PLAT MONUMENT

FOUND REBAR AS NOTED

□G **GAS METER**

ALDER TREE

MAPLE TREE

WATER LINE

RIGHT-OF-WAY

---- RIGHT-OF-WAY CENTER LINE

EDGE OF ASPHALT

BUILDING

/// CONC. WALL

PROPERTY BOUNDARY

CONCRETE PATH & PARKING

BUILDING OUTLINE FROM ASSESSOR

DECIDUOUS TREE

FOUND IRON PIPE AS NOTED


FOUND 1/2" REBAR W/CAP "HAI 34137"


FOUND PK NAIL WITH WASHER HAI 34137

I DETERMINED THAT THE PLAT DISTANCE SHOWN FOR THE SOUTHWEST CURB RETURN IS INCORRECT. BY HOLDING A DISTANCE OF 49.96 FEET THE GEOMETRY OF RADIUS LENGTH AND CENTRAL ANGLE WORK. I HELD THE CALCULATED DISTANCE ALONG THE

KING CO RECORDER'S CERTIFICATE # 20161206990020, BY FOX SURVEYING

KING CO RECORDER'S CERTIFICATE # 9709109004, BY CONCEPT ENGINEERING INC.





HORIZONTAL DATUM: BASIS OF BEARING: CENTER LINE OF FOREST AVE SE BEARS SOUTH 00°05'56"EAST PER REPLAT OF A PORTION OF LAKE ISLE VOL 26 OF PLATS, PAGE 13, KING COUNTY, WA

> NAVD 88 GEOID 12A ESTABLISHED BY GPS

SITE BENCHMARKS:

TBM #1: FOUND 3/4" IRON PIPE W/TACK IN CASE C/L FOREST AVE SE & 81ST AVE SE ELEV: 101.28'

TBM #2: FOUND PK NAIL SET 1'W OF EAST EDGE OF PAVEMENT OF 81ST ST SE & DRIVEWAY TO #8201 SE 48TH ST

SURVEY NOTES:

1) SURVEY PROCEDURES & EQUIPMENT: SECTION CONTROL: TOPCON GNSS GR-3 RECEIVERS.

ELEV: 171.94'

ON SITE CONTROL AND STAKING: TOPCON GNSS GR-3 RECEIVERS AND/OR FIELD TRAVERSE & 10" TOTAL STATION.

2) THE GPS SURVEY PERFORMED FOR THIS SURVEY MEETS OR EXCEEDS THOSE STANDARDS CONTAINED IN WAC 332-130-160. THE FIELD TRAVERSES USED IN THIS SURVEY MEET OR EXCEED THOSE STANDARDS CONTAINED IN WAC 332-130-090.

3) GPS CONTROL: WASHINGTON STATE REFERENCE NETWORK (WSRN) GPS NETWORK. HORIZONTAL DATUM IS NAD83 (NA2011) EPOCH 2010.00. VERTICAL DATUM IS NAVD88 GEOID 12A.

3) DISTANCES ARE IN FEET AND DECIMALS THEREOF.

4) ALL CONTROLLING MONUMENTS SHOWN ARE OF RECORD, ARE LOCALLY ACCEPTED AS REPRESENTATIVE OF THEIR PURPORTED POSITIONS, AND WERE VISITED DURING THE COURSE OF THIS SURVEY UNLESS OTHERWISE NOTED.

5) THIS SURVEY DOES NOT PURPORT TO SHOW ALL EASEMENTS.

LEGAL DESCRIPTION:

DESCRIBED LINE.

(PER STATUTORY WARRANTY DEED AUDITOR'S FILE # 20150521001767, RECORDS OF KING COUNTY, WASHINGTON)

LOTS 41, 42 AND 43 OF REPLAT OF A PORTION OF LAKE ISLE, AS PER PLAT RECORDED IN VOLUME 26 OF PLATS, PAGE 13, RECORDS OF KING COUNTY, AUDITOR.

BEGINNING AT THE SOUTHWEST CORNER OF SAID LOT 41; THENCE NORTH 18'30'38" EAST ALONG THE WESTERLY LINE THEREOF 52.31 FEET AND THE TRUE POINT OF BEGINNING OF SAID LINE; THENCE SOUTH 76°33'06" EAST 165.27 FEET TO A POINT ON THE EASTERLY LINE OF

EXCEPT THAT PORTION OF SAID LOT 41 LYING NORTHEASTERLY OF THE FOLLOWING

SAID LOT 41 AND THE TERMINUS OF SAID LINE.

SITUATE IN THE CITY OF MERCER ISLAND, COUNTY OF KING, STATE OF WASHINGTON.

SURVEYOR'S CERTIFICATION:

LOCATIONS SHOWN ON THIS MAP ARE BASED ON A FIELD SURVEY BY HARMSEN AND ASSOCIATES ON MAY 2ND, 2018 AND RECORDED IN FIELDBOOK 1178. BOUNDARY INFORMATION IS BASED UPON THE REPLAT OF A PORTION OF LAKE ISLE, RECORDED IN VOLUME 26 OF PLATS, PAGE 13, RECORDS OF KING COUNTY AUDITOR, WASHINGTON AND RECORD OF SURVEY RECORDING NUMBER 20161206900020, RECORDS OF KING COUNTY, WASHINGTON. LOCATION SURVEY WAS PERFORMED UNDER MY SUPERVISION IN CONFORMANCE WITH APPLICABLE STATE AND INDUSTRY STANDARDS AT THE REQUEST OF RON BERESKY IN APRIL, 2018.

INDEX KEY

T24N-R4E

5/17/18

RICHARD F. CARPENTER, PROFESSIONAL LAND SURVEYOR REGISTRATION NO. 34137

(DATE)

C:\USERS\ROGERL\LOCAL SETTINGS\TEMP\ACPUBLISH_5068\BERESKY TOPO.DWG 05/18/2018

UNPUBLISHED WORK COPYRIGHT @ 2018 BY HARMSEN & ASSOCIATES IN

REVISIONS





DRAWING:

