



November 8, 2023

Andrew Leon
9611 SE 36th St
Mercer Island, WA 98040

RE: CAO23-016
RFI #1
7235 East Mercer Way

Dear Andrew,

The following issues have been addressed with our revisions.

Geotechnical Engineering:

1. Please resolve the conflict between the geotechnical engineer's foundation recommendations in the geotechnical report and the foundations shown on the project drawings.

The revised plan set now reflects the geotechnical engineer's foundation recommendations. Please see sheet S-4.

2. Please provide a plan review letter and updated statement of risk from the geotechnical engineer of record.

A plan review letter and updated statement of risk from the geotechnical engineer of record has been provided with the revisions in a separate document.

Sincerely,

Melissa Dow
Weaver Construction, LLC
melissa@weaverconstructionco.com
253.670.5173