



October 19, 2022

Ms. Madison Johnson  
Seaborn Pile Driving  
1080 West Ewing Street  
Seattle, Washington 98119

**RE: Post-Design Plan Review  
George Residence  
9607 Southeast 72nd Street  
Mercer Island, Washington 98040  
RGI Project No. 2022-439-1**

References: Geotechnical Engineering Report, prepared by The Riley Group, Inc. dated August 12, 2022.  
Site plans (A1.0 to A13.0), prepared by Seaborn Pile Driving updated September 27, 2022

Dear Ms. Johnson:

As requested, The Riley Group, Inc. (RGI) has performed a geotechnical study for the above referenced site and prepared the referenced geotechnical engineering report. As requested by the City of Mercer Island, RGI has performed a post-design review of the referenced plans per the City of Mercer Island City Code (MICC) 19.07.160.B.3. The landslide hazard area will be modified or the development has been designed so that the risk to the site and adjacent property is eliminated or mitigated such that the site is determined to be safe.

Based on the current design and our geotechnical study, in our professional opinion; the proposed improvement will not have negative impact to the neighboring properties if the geotechnical recommendations in the referenced report are incorporated into the project design and construction. The risk of damage to the proposed development and from the development to adjacent properties from soil instability will be minimal.

If you have any questions or require additional information, please contact us.

Respectfully submitted,

**THE RILEY GROUP, INC.**



Ricky R. Wang, PhD, PE  
Principal Engineer

*Corporate Office*  
17522 Bothell Way Northeast  
Bothell, Washington 98011  
Phone 425.415.0551 ♦ Fax 425.415.0311

[www.riley-group.com](http://www.riley-group.com)