

Bates Number	Description
1001	Original Geotechnical Survey for 6950 (from Building Permit 2207-019)
1002	Geotechnical Survey from CAO23-011
1003	Plan Set from CAO23-011
1004	Arborist report (Selby)
1005	Mercer Island Zoning Code 1960
1006	Index Page and Map Block for Official Topographic Base Map of 1963
1007	Topographic Map page C-2
1007.1	Topographic Map page C-2 zoom
1008	PRE21-053
1009	McHarg email
1010	City meeting notes showing retaining walls built with illegal methods
1011	Pre21-053 data showing unpermitted addition
1013	Letter to Ms. Strand from appellants and neighbors about tree
1014	Kenney email
1015	Strand TPP
1017	7030 SE Maker inspection report - 1985
1018	7030 SE Maker building plan
1019	7030 SE Maker geotech report 1981
1020	Uniform Building Code of 1958
1021	Ordinance 5
1022	Ordinance 16
1023	7145 Geotech report
1024	Comparison of retaining wall in Webster's, UBC, MICC
1025	Letter from applicant to city, 11/16/21
1026	Comparison of 1963 and 2021 elevations
1027	Appellants' Memorandum