

LEGEND

lacktriangle	FOUND MONUMENT AS DESCRIBED	— OHP—	OVERHEAD POWER	
0	FOUND REBAR AS DESCRIBED	—они—	OVERHEAD UTILITIE	
X	TACK IN LEAD FOUND	-X-	CHAINLINK FENCE	
•	SET 5/8" X 24" IRON ROD	——	WOOD FENCE	
	W/1" YELLOW PLASTIC CAP	××××××××××××××××××××××××××××××××××××××	CONCRETE WALL	
P	POWER METER			
Ø	UTILITY POLE		ROCKERY	
0	GAS METER		ASPHALT SURFACE	
	SANITARY SEWER CLEANOUT			
	SANITARY SEWER MANHOLE	A	CONCRETE SURFAC	
M	WATER VALVE		GRAVEL SURFACE	
Q	FIRE HYDRANT			
\blacksquare	WATER METER	CE	CEDAR	
	SIGN	DS	DECIDUOUS	
—ss-	APPROXIMATE LOCATION SANITARY	MP	MAPLE	
	SEWER LINE	DF	DOUGLAS FIR	
—sd-	_ APPROXIMATE LOCATION STORM DRAIN LINE	PI	PINE	
		* INDICA	* INDICATES MULTI-TRUNK	

LEGAL DESCRIPTION

THAT PORTION OF THE SOUTH 100 FEET OF THE NORTH 700 FEET OF GOVERNMENT LOT 1, SECTION 19, TOWNSHIP 24 NORTH, RANGE 5 EAST, W.M., IN KING COUNTY,

WASHINGTON LYING WEST OF E. MERCER WAY EXCEPT THE PORTION THEREOF LYING WEST OF A LINE BEGINNING AT A POINT ON THE SOUTH LINE OF THE NORTH 700 FEET OF SAID GOVERNMENT LOT 1, WHICH POINT BEARS S 89°46'00" E ON SAID SOUTH LINE A DISTANCE OF 543.09 FEET FROM THE WEST LINE OF SAID GOVERNMENT LOT 1; THENCE N 15°20'00" W 103.69 FEET TO THE TERMINUS OF THE

SITUATE IN THE CITY OF MERCER ISLAND, COUNTY OF KING, STATE OF WASHINGTON.

BASIS OF BEARINGS

ACCEPTED A BEARING OF S 02°38'45" E ALONG THE CENTER LINE OF EAST MERCER WAY BETWEEN FOUND MONUMENTS IN CASE PER RECORD OF SURVEY UNDER KING COUNTY RECORDING NO. 198708039001.

PROJECT INFORMATION

SURVEYOR: SITE SURVEYING, INC. 21923 NE 11TH ST SAMMAMISH, WA 98074 PHONE: 425,298,4412 AMIR & SARAH BASTAWROUS PROPERTY OWNER: 4909 E MERCER WAY MERCER ISLAND, WA 98040 TAX PARCEL NUMBER: 216200-0230 PROJECT ADDRESS: 4909 E MERCER WAY MERCER ISLAND, WA 98040 ZONING: JURISDICTION: CITY OF MERCER ISLAND 17,399 S.F. (± 0.399 ACRES) AS SURVEYED PARCEL ACREAGE:

GENERAL NOTES

- 1. THIS SURVEY WAS COMPLETED WITHOUT BENEFIT OF A CURRENT TITLE REPORT. EASEMENTS AND OTHER ENCUMBRANCES MAY EXIST ON THIS PROPERTY THAT ARE NOT SHOWN HEREON.
- INSTRUMENTATION FOR THIS SURVEY WAS A 5-SECOND SPECTRA PRECISION FOCUS 30 TOTAL STATION. PROCEDURES USED IN THIS SURVEY MEET OR EXCEED STANDARDS SET BY WAC 332-130-090.
 THE INFORMATION ON THIS MAP REPRESENTS THE RESULTS OF A SURVEY MADE IN MAY 2018 AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL
- CONDITIONS EXISTING AT THAT TIME.
 4. UTILITIES SHOWN ON THIS SURVEY ARE BASED UPON ABOVE GROUND OBSERVATIONS AND AS-BUILT PLANS WHERE AVAILABLE. ACTUAL LOCATIONS OF
- UNDERGROUND UTILITIES MAY VARY AND UTILITIES NOT SHOWN ON THIS SURVEY MAY EXIST ON THIS SITE.

 5. ALL MONUMENTS WERE LOCATED DURING THIS SURVEY UNLESS OTHERWISE

VERTICAL DATUM & CONTOUR INTERVAL

ELEVATIONS SHOWN ON THIS DRAWING ARE ON AN ASSUMED



2.0' CONTOUR INTERVAL - THE EXPECTED VERTICAL ACCURACY IS EQUAL TO 1/2 THE CONTOUR INTERVAL OR PLUS / MINUS 1.0' FOR THIS PROJECT.

