

# **TECHNICAL MEMORANDUM**

TO:	Megan Campbell, Harbor Consulting Engineers	
FROM:	Brad Thiele, Northwest Environmental Consulting, LLC	
DATE:	August 21, 2019, revised March 31, 2020	
SUBJECT:	Slope Re-vegetation Approach	
PROJECT:	Knopf Steep Slope Stabilization	

#### INTRODUCTION

Ed and Donna Knopf are stabilizing a slope that failed in early 2019. The City of Mercer Island requires that a re-vegetation plan be completed to stabilize disturbed areas. This technical memorandum summarized the replanting efforts and establishment.

#### KNOPF PROPOSED SLOPE RE-VEGETATION APPROACH

# **Planting Plan**

The proposed mitigation will restore approximately 6,065 square feet of disturbed steep slope with native vegetation. Conditions at the site include seasonal seepage from the slope. Plants were selected that will tolerate wet and wet to dry conditions at the site. Table 1 lists the plant species that will be installed. See Drawings W-1 for additional details.

Common Name	Scientific Name
Cascara	Rhamnus purshiana
Pacific crabapple	Malus fusca
Vine maple	Acer circinatum
Black hawthorn	Crataegus douglasii
Snowberry	Symphoricarpos albus
Nootka rose	Rosa nutkana
Red osier dogwood	Cornus sericea
Clustered rose	Rosa pisocarpa

Table 1. Proposed nativ	e species to be used i	n the planting plan
-------------------------	------------------------	---------------------

Pacific ninebark

# **Mitigation Goals**

Mitigation goals are as follows:

•Plant approximately 6,065 square feet with native plants to expand to restore the steep slope disturbance.

•Control Himalayan blackberry and other invasive plant species in the restored area.

## **Performance Standards**

Plantings shall maintain a 100% survival for the first year and achieve 80% survival in years 2, 3, 4 and 5. For proper functioning, species diversity will be maintained. The planting areas will maintain a minimum of 4 shrub species for the 5-year monitoring period.

Invasive species shall be controlled so that they do not reach more than 10% aerial coverage for the 5-year monitoring period.

## **Schedule and Maintenance**

Plantings shall be containerized plants or bare root. Watering of the installed plants may be required if drought conditions occur during the summer months. Invasive plants will be removed throughout the year as they occur.

# **Proposed Monitoring, Reporting and Contingency**

To ensure that the performance standards are met, plantings will be counted in August or September for survival for the first year. The site will be monitored for Five years from the time of completion of site construction by a qualified individual(s) who is experienced or trained in vegetation and monitoring techniques.

Valid monitoring data are critical to making meaningful management decisions that help the mitigation site meet its objectives. Monitoring plans are based on mitigation site conditions and plant community development. These factors together with the wetland mitigation objectives are to be incorporated into a site-specific monitoring plan that will be developed at the beginning of each monitoring season. The annual monitoring plan will use standard vegetation sampling methodology to measure site performance standards such as actual counts, line intercept methods or belt transect methods.

The monitoring team will be responsible for taking a representative sample of the site and determining an appropriate sample size.

#### **Monitoring Reports**

Monitoring reports will be completed and submitted to the City by December 31 for each of the monitoring years.

# **Contingency Actions**

All dead plantings will be replaced so that 100% survival is reached for the first year. A sub-sample can be completed to assure that the 100% survival is reached. In years 2, 3, 4, and 5 all plantings will maintain an 80% survival rate for five years.

Himalayan blackberry, English ivy, and English holly will also be manually removed from the restoration area if they reach 10% or greater coverage during the five-year period.

