

SEASONAL DEVELOPMENT EMERGENCY PROCEDURES

OWNER: JOHN SULLIVAN
CONTRACTOR: WLSS, LLC
BUILDING PERMIT #: 2301-185
ADDRESS: 3024 69TH AVE SE, MERCER ISLAND, WA, 98040

PROCEDURES:

If Work on site is done in accordance with the Geotechnical report produced by Cobalt Geosciences, dated 06.27.2023, it is the general consensus that the site is not an erosion, slide or steep slide hazard. However, in the event of an emergency concerning the above, the following steps will be taken

1. Site shut down and evacuation of workers (if necessary: based on severity of events)
2. Assessment of situation/ severity.
3. Look for broken utilities (Notify appropriate branch)
4. Assess safety of building, foundation, and/or roadways
5. If necessary: contact local officials (fire / police / public works)
6. If necessary: contact affected neighbors (help evacuate)
7. Safely divert ant run-off
8. Contact Geotech advisor for corrective actions to be taken
9. Stabilize, make repairs, fill and cover with appropriate cover materials as required.