### **Ecological No Net Loss Assessment Report**

**Prepared for** 

Jenn Henry 6802 96<sup>th</sup> Ave SE Mercer Island, WA 98040

Prepared by

W Northwest Environmental Consulting, LLC

Northwest Environmental Consulting, LLC 600 North 36<sup>th</sup> Street, Suite 423 Seattle, WA 98103 206-234-2520

September 2022

### Purpose

The purpose of this report is to fulfill the requirements of City of Mercer Island Municipal Code (MICC) 19.07.110 Shoreline Master Program by assessing overall project impacts and proposed mitigation to determine if the project meets the "No Net Loss" General Regulation of the Shoreline Master Program.

No Net Loss is defined as "An ecological concept whereby conservation losses in one geographic or otherwise defined area are equaled by conservation gains in function in another area."

Permits are being applied for a dock extension, bulkhead repair, and associated moorage improvements.

### Location

The subject property is located at 6802 96<sup>th</sup> Ave SE (King County parcel number 2580700005) in the City of Mercer Island, Washington (see Appendix A – Sheet A1.0). The parcel is on the waterfront of Lake Washington, a shoreline of the state, that contains several endangered fish species listed under the Endangered Species Act and Washington State designated priority fish species.

### **Project Description**

The proposed construction involves driving 8 new 8-inch epoxy coated steel piles and constructing a new deck with grated decking material at the waterward side of the existing dock. A single mooring pile will be removed. The existing unpermitted boat lift will be moved waterward towards the end of the new dock extension. ThruFlow grated decking will be used for decking on the new dock.

The existing bulkhead will be repaired by removing 74 linear feet of the existing rock bulkhead and removal of the existing submerged concrete slabs. The new bulkhead will be reconstructed by constructing a new rock bulkhead along the shoreline and around the 181 square foot beach cove with stairs.

The existing personal watercraft lift and existing boat lift were not permitted and are included in this analysis to be permitted. See Appendix A – Sheets A2.0 to A 6.0).

During construction, a floating boom will surround the work barge and dock. A silt curtain will be used during bulkhead repair. (See Appendix A – Sheets A7.0)

A shoreline vegetation plan is proposed, that will add 2 native conifer trees and 3 native shrubs and preserve the existing vegetation. These shoreline plantings will provide shade and allow beneficial allochthonous material to enter the lake along the shoreline (see Appendix A – Sheet A8.0 and a9.0).

Project drawings are included in Attachment A.

### Approach

Northwest Environmental Consulting LLC (NWEC) biologist Brad Thiele conducted a site visit on September 9, 2022 to evaluate conditions on site and adjacent to the site. NWEC also

consulted the following sources for information on potential critical fish and wildlife habitat along this shoreline:

- Washington Department of Fish and Wildlife (WDFW): Priority Habitats and Species online database (http://apps.wdfw.wa.gov/phsontheweb/)
- WDFW SalmonScape online database of fish distribution and ESA listing units (https://apps.wdfw.wa.gov/salmonscape/)
- Mercer Island GIS online database (https://chgis1.mercergov.org/Html5Viewer/Index.html?viewer=PubMaps&viewer=PubM aps)

### **Site Description**

The subject property is a shoreline tract in a residential neighborhood. It has shoreline on its eastern boundary with single-family homes to the north and south along the shoreline.

The only existing structures on the property are the house, and the existing wood decked dock.

The shoreline is armored with a basalt bulkhead. The substrate of the lake is sand and gravel with some remnant Eurasian milfoil still present towards the end of the dock.

The shoreline is lawn with ornamental beds along the top of the bulkhead and fence lines. The neighboring properties are similar in shoreline armoring and have docks. See attached photos in Appendix B- Photos.

### **Species Use**

WDFW's PHS mapping and SalmonScape mapping tools show the following salmonid species using Lake Washington for migration and/or rearing: residential coastal cutthroat (*Oncorhynchus clarkii*), winter steelhead (*O. mykiss*), Dolly Varden/bull trout (*Salvelinus malma*), sockeye salmon (*O. nerka*), fall Chinook (*O. tshawytscha*), coho salmon (*O. kisutch*), and kokanee (*O. nerka*). The SalmonScape database maps the site as accessible to the Endangered Species Units (ESU) of Threatened Chinook and steelhead. Juveniles migrate and may rear in the waters near the project when traveling from spawning sites on other lake tributaries to the lake's outlet at the Hiram M. Chittenden Locks. The project site is accessible to any fish migrating or rearing in the lake. The shoreline is mapped as or very near a sockeye salmon spawning location.

Priority Habitats and Species mapping, maps a biodiversity area at Pioneer Park about 1,600 feet to the west but no other terrestrial priority species or habitats at or near the site.

The City of Mercer Island GIS Portal does not indicate any environmental features at the site.

### **Project Impacts and Conservation Measurements**

#### Direct Impacts:

**Sediments:** Sediment disturbance will occur below the OHWM and along the shoreline of Lake Washington during pile removal installation, and removal of a section of the bulkhead.

Additionally, the tug and barge propwash may disturb sediments temporarily when making trips to/from the site.

Impacts to sediments should be minimal from installation and removal of the pilings.

The reconstruction and removal of the bulkhead has the potential to create a significant sediment plume. A weighted silt curtain will be installed around the perimeter to contain any suspended sediments that occur during construction of the bulkhead.

**Shoreline:** Removing the bulkhead will improve shoreline conditions by removing a section of bulkhead that creates a reflecting wave at high water that can cause erosion of shoreline sediments. In addition the beach cove can be beneficial to outmigrating salmonids at high water.

Planting additional native vegetation, including a native cedar tree, will increase the habitat functions of the shoreline by creating shade along the shoreline that will be an improvement from the existing baseline habitat conditions at the project site. These plants will provide overhanging cover for fish, structural diversity for birds and wildlife, detritus for aquatic invertebrates and long-term recruitment of woody material and other allochthonous food sources. The proposed planting plan is included (see Appendix A - Sheet A8.0).

**Lakebed:** Construction of the dock extension includes driving 8 8-inch pilings and removal of 1 10-inch pile. This will result in 2.3 square feet of lake bottom displacement.

**Noise:** Construction equipment will create noise audible to neighbors and in-water. Noise disturbance will be short-term and should have negligible effects on fish and wildlife in the area. Work will be completed during the in-water work window when juvenile fish are not expected to be present.

**Potential spills:** Short-term risks include the potential for petroleum spills that can occur with any equipment operation. The level of impact to the aquatic environment is expected to be minor because a trained crew will be onsite that will implement spill containment measures should a spill occur.

**Shading:** The proposed dock will increase overwater coverage by 233 square feet. The proposed decking will be ThruFlow grated decking. Grated decking allows more light to penetrate the waters below a dock, which can increase productivity in the water column, and reduce the full shade favored by salmonid predators. Salmonid predators are known to use hard shadowing under solid-decked docks to ambush juvenile salmonids. Reducing these hard shadows limits their ability to effectively hunt salmonids. In addition, hard shadowing may reduce juvenile salmonid outmigration times when encountered along the shoreline.

ThruFlow grated decking has measured performance at 43 percent light penetration (ThruFlow, 2021). Thus, the increase in lighting under the pier is effectively 57% of the area of a solid decked structure. Table 1 provides a summary of effective coverage:

	Existing/ Proposed	Proposed grated	Conversion		Reduction in effective coverage
New Grated Dock (SF)	0	233	0.57	133	100

#### Table 1 – Effective coverage

The use of grated decking at the site reduces the effective coverage of the new structure by 100 square feet.

In addition the new dock configuration will place moorage into water 7 to 12 feet deep.

**Recreational Boating:** The project supports continued recreational boating, which has been identified as a limiting factor for salmonid populations in Lake Washington. The pier will not introduce additional boating to Lake Washington, as the owners could still access the lake from a public boat launch or private moorage facility.

#### Other Conservation measures:

**Work window:** The work will be completed during the prescribed in-water work window for this area of Lake Washington (July 16 to December 31). Operating within this time frame helps protect Chinook salmon, steelhead, bull trout and other salmonid fish species by doing work when juvenile fish are not expected to be present.

**Best Management Practices:** Applicable BMPs will be used, such as a floating boom around the in-water work area, to contain any floating debris that may escape during construction. The barge will have a perimeter containment sock to absorb oil and grease that might inadvertently wash from the barge during construction. A silt curtain will be used to contain turbidity that may be generated from removal of a section of existing bulkhead.

Hazardous material containment supplies such as spill absorbent pads and trained personnel will be required onsite during any phase of construction where machinery is in operation near surface waters.

### Conclusion

Juvenile Chinook salmon, and other salmonids, rear and migrate along the Lake Washington shoreline.

There will be temporary impacts from noise and disturbed sediments during construction and bulkhead repair. Construction disturbance and dock reconfiguration will degrade ecological conditions at the site by increasing overwater coverage at the site. The effects of construction will be short term. The dock will use grated decking to minimize the effective overwater coverage to a net gain of 133 square feet. The grating reduces the hard shadows favored by salmonid predators and increases productivity under the pier. In addition, the new structure is in deeper water more than 30 feet from shore. Overwater structures may slow juvenile salmonid outmigration times. Constructing the new moorage away from shore will reduce the chances of delaying outmigrating juvenile salmonids.

The project will displace about 2.3 square feet of lakebed from installation of new pilings.

Ecological conditions at the site will be improved by placing the watercraft lift in the deeper water to prevent or reduce sediment disturbance during docking and castoff from propwash over the existing condition.

A shoreline planting plan will be implemented that will add native trees and shrubs to the shoreline that will provide natural shading, allochthonous food sources and will eventually be a source of woody materials that will improve shoreline conditions at the site in the long-term.

Removing the concrete slabs will restore shoreline substrates at the cove.

The project will minimize construction effects on the environment by following the prescribed fish window and using applicable BMPs to prevent construction spills, turbidity, and floating

debris from escaping the area. The construction crew will retrieve all dropped items from the bottom and dispose of them properly.

This project has been designed to meet current residential dock standards and will use Best Management Practices to reduce project impacts. The conservation measures are designed to improve ecological functions or prevent further degradation of habitat **and will result in No Net Loss of ecological functions**.

### **Document Preparers**

Brad Thiele

Biologist

28 years of experience


Northwest Environmental Consulting, LLC (NWEC)

NWEC followed standard acceptable field methods and protocols at the time work was performed. These standards may include delineation of wetland and stream boundaries, characterization, rating, functional analyses, impact assessments and mitigation of impacts. The conclusions and findings in this report are based on field observations and measurements and represent our best professional judgment and to some extent rely on other professional service firms and available site information. Within the limitations of project scope, budget, and seasonal variations, we believe the information provided herein is accurate and true to the best of our knowledge. Northwest Environmental Consulting does not warrant any assumptions or conclusions not expressly made in this report or based on information or analyses other than what is included herein.

- King County. 2022. King County iMap. Online database. Accessed September 2022 at https://gismaps.kingcounty.gov/iMap/
- Washington Department of Fish and Wildlife (WDFW). 2022. Priority Habitats and Species. Online database. Accessed September 2022 at http://apps.wdfw.wa.gov/phsontheweb/
- WDFW. 2022. SalmonScape. Online database. Accessed September 2022 at http://apps.wdfw.wa.gov/salmonscape/

## Appendix A: Project Drawings

# SITE PLAN




#### Pin: 258070-0005

Legal Description: FLOODS LAKE SIDE TRS DIV #3 LOT B MERCER ISLAND SHORT PLAT HOLYOKE AF #7507230710 SD PLAT DAF LOT 1 BLK 1 FLOODS LAKE SIDE TRS DIV #3 TGW SH LDS ADJ

Plat Block: 1 Plat Lot: 1

LAT: 47.54198 LONG: -122.21001



	NWS-2022- PAGE 1 OI	
struct a 233 SQFT extension, re s, and permit (2) existing boat li	SHEET	2
	Datum: CORPS OF ENGINEERS 1919 NE Quarter Of Section 30, Township 24, Range 05	AUJACCTIL OWITELS. STIVERS JEAN GILLILAND-TTEE 8810 96TH AVE SE 98040
.0	VEERS 1919 Township 24, Range 05	NIEDERMAN CHRISTOPHER A 6800 96TH AVE SE 98040
	Applicant: Henry Residence 6802 96TH AVE SE Mercer Island, WA 98040	Created:
R-A	County: Location:	Last Updated: 8/2/2022 4:28 PM Zion
	County: King County Location: Lake Washington	22 4:28 PM Zion

# GENERAL NOTES:

### MATERIALS SPEC LIST:

**Decking Material:** FRPP - Fiberglass reinforced polypropylene Light permeable percentage:

- \* Surface 43%
- \* 18" Dock Height 61%

### Sewer:

\* All sewer is field verified by probing the lake bed manually during the allowed work windows for the area.

### Piles:

- \* All new piles are epoxy coated steel piles \*size varies, see plan set
- \* Piles are driven using the vibro method

#### CODE REFERENCES: Mercer Island

We are applying for the permit to be reviewed under the:

### "Alternative Development Standards" per MIMC 19.13050(F)(3).

The code official shall approve moorage facilities not in complian standards in subsection (F)(1) or (F)(2) of this section subject to be Engineers and Washington Department of Fish and Wildlife approximates and all other applicable provimet:

i. The dock must be no larger than authorized through state and Shoreline Master Program | Mercer Island City Code Page 30 of is current through Ordinance 20C-13, passed June 16, 2020.

#### The dock is no longer than authorized.

ii. The maximum width must comply with the width of moorage standards specified in subsection D of this section (Table D);

#### The maximum width is within compliance.

iii. The minimum water depth must be no shallower than author approval;

#### The minimum water depth is within compliance.

iv. The applicant must demonstrate to the code official's satisfact will not create a net loss in ecological function of the shorelands

#### The No Net Loss report is attached.

v. The applicant must provide the city with documentation of ap facilities by both the U.S. Army Corps of Engineers and the Wash Wildlife.

#### The plan set is is review by CORPS and WDFW.

Mitigation" Disturbance of bank vegetation shall be limited to the min accomplish the project. Disturbed bank vegetation shall be replaced we herbaceous and/or woody vegetation. Herbaceous plantings shall occur completion of construction. Woody vegetation components shall be p whichever occurs first. The applicant shall take appropriate measures

Last permit issued for property: Permit # 0408-290 Sep 29, 2004 Dock established/constructed: 5/1/1967





Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119

Office: 206-236-1700 ext. 3 www.seabornpiledriving.com

Scope of Work: We propose to drive (8) new steel piles, remove (1) existing mooring pile, cons 74 LnFt of existing bulkhead, remove 12.44 cu yd concrete slabs, install a new cove with stairs


	King County Lake Washington	22 4:28 PM Zion
nce with the development both U.S. Army Corps of roval to an alternate project visions in this chapter shall be	County: Location:	-ast Updated: 8/2/2022 4:28 PM Zion
d federal approval; Ch. 19.13 34 The Mercer Island City Code		_
e facilities standards specified in	Applicant: Henry Residence 6802 96TH AVE SE Mercer Island, WA 98040	
ized through state and federal	ant: Hen 6802 Merce	
ction that the proposed project s; and	Applica	Created
oproval of the moorage nington Department of Fish and nimum amount necessary to	IEERS 1919 Township 24, Range 05	NIEDERMAN CHRISTOPHER A 6800 96TH AVE SE 98040
with native, locally adapted ur within 48 hours of the planted in the fall or early winter, s to ensure revegetation success;	Datum: CORPS OF ENGINEERS 1919 NE Quarter Of Section 30, Township 24,	Adjacent Owners: stivers jean gilliland-ttee 6810 96th ave se 98040
struct a 233 SQFT extension, repair , and permit (2) existing boat lifts.	SHEET	2.0
	NWS-2022	






# PIER DETAILS - EXISTING/PROPOSED PLAN VIEW

#### LEGEND



○ (1) EXISTING MOORING PILE - TO BE REMOVED





Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119 Office: 206-236-1700 ext. 3

www.seabornpiledriving.com


Scope of Work: We propose to drive (8) new steel piles, remove (1) existing mooring pile, cons 74 LnFt of existing bulkhead, remove 12.44 cu yd concrete slabs, install a new cove with stairs,

struct a 233 SQFT extension, repair s, and permit (2) existing boat lifts.		SHEET 5.0	
	Datum: CORPS OF ENGINEERS 1919 NE Outstar Of Section 30 Townshin 21 Banze 05	Adjacent Owners:	STIVERS JEAN GILLILAND-TTEE NIEDERMAN CHRISTOPHER A 6810 96TH AVE SE 98040 6800 96TH AVE SE 98040
 5′-10″ 	Applicant: Henry Residence	6802 96TH AVE SE Mercer Island, WA 98040	Created:
	County:	Location:	Last Updated: 8/2/2022 4:28 PM Zion
	King County	Location: Lake Washington	22 4:28 PM Zion

15' WATER

DEPTH

# PIER DETAILS EXISTING/PROPOSED - SECTION VIEW



SECTION VIEW: A'-A'




Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119 Office: 206-236-1700 ext. 3

www.seabornpiledriving.com

Scope of Work: We propose to drive (8) new steel piles, remove (1) existing mooring pile, cons 74 LnFt of existing bulkhead, remove 12.44 cu yd concrete slabs, install a new cove with stairs,

	County: Location:	Last Updated: 8/2/2022 4:28 PM Zion
OHWL 15' LAKE WASHINGTON	Applicant: Henry Residence 6802 96TH AVE SE	Mercer Island, WA 98040 Created:
	Datum: CORPS OF ENGINEERS 1919 NE Quarter Of Section 30, Township 24, Range 05	Adjacent Owners: stivers Jean gilliland-ttee Niederman christopher a 6810 96TH ave se 98040 6800 96TH ave se 98040
struct a 233 SQFT extension, repair s, and permit (2) existing boat lifts.	SHEET	0.9 922-XXX
		6 OF 13

# **BMP INFORMATION**



1080 W Ewing St

FABOR

ESTD 1947

Seattle, WA 98119

Office: 206-236-1700 ext. 3


www.seabornpiledriving.com


#### **BMP NOTES:**

- 1. The project manager shall designate an appropriate number of con site and adjacent areas for protected species, including the preser
- 2. Visual surveys shall be made prior to the start of work each day, a any break of more than an hour. Periodic additional visual surveys recommended.
- 3. All in-water work shall be done during the in-water work window fo difference between the USCOE and WDFW work windows, the ov
- 4. All pile driving and extraction shall be postponed or halted when of are observed within 50 yards of that work, and shall only begin/res departed the area.
- 5. When piloting vessels, vessel operators shall operate at speeds a vessels, and minimize substrate scour and mobilization of bottom
- Β. No contamination of the marine environment shall result from pro
- 1. Appropriate materials to contain and clean potential spills shall be site and/or aboard project-related vessels.
- 2. The project manager and heavy equipment operators shall perform for cleanliness and leaks. All heavy equipment operations shall be detected, and shall not proceed until the leak is repaired and the e
- 3. To the greatest extent practicable, utilize biodegradable oils for eq near water.
- 4. Fueling of land-based vehicles and equipment shall take place at preferably over an impervious surface. Fueling of vessels shall be
- 5. Turbidity and siltation from project-related work shall be minimized use of erosion control practices, effective silt containment devices. adverse weather and tidal/flow conditions.
- 6. All wastes shall be collected and contained for proper disposal at appropriate for the material(s).
- 7. When removing piles and other similarly treated wood, containment area. Wood debris, oils, and any other materials released into lak and properly disposed of at approved disposal sites.
- 8. All in- and over-water wood cutting would be limited to the minimu component, and all cutting work should be enclosed within floating
- 9. When removing piles, no actions shall be taken that would cause waters.
- 10. Above-water containment shall be installed around removed piles returning to lake waters.
- 11. Construction staging (including stocking of materials, etc.) will occu
- 12. All Exposed wood to be used on the project will be treated with a

		gton
	<ul> <li>BMP NOTES:</li> <li>A. Constant vigilance shall be kept for the presence of protected fish species during all aspects of the proposed action, particularly during in-water activities such as vessel movement, deployment of anchors &amp; spuds, pile driving, dredging, and placement of gravels and other fill.</li> <li>1. The project manager shall designate an appropriate number of competent observers to survey the project site and adjacent areas for protected species, including the presence of fish as conditions allow.</li> <li>2. Visual surveys shall be made prior to the start of work each day, and prior to resumption of work following any break of more than an hour. Periodic additional visual surveys throughout the work day are strongly recommended.</li> <li>3. All in-water work shall be done during the in-water work window for the waterbody. Where there is a difference between the USCOE and WDFW work windows, the overlap of the two shall apply.</li> <li>4. All pile driving and extraction shall be postponed or halted when obvious aggregations or schooling of fish are observed within 50 yards of that work, and shall only begin/resume after the animals have voluntarily</li> </ul>	County: King County Location: Lake Washington Last Updated: 8/2/2022 4:28 PM Zion
DETAIL 1.2	<ul> <li>departed the area.</li> <li>When piloting vessels, vessel operators shall operate at speeds and power settings to avoid grounding vessels, and minimize substrate scour and mobilization of bottom sediments.</li> <li>No contamination of the marine environment shall result from project-related activities.</li> <li>Appropriate materials to contain and clean potential spills shall be stored and readily available at the work site and/or aboard project-related vessels.</li> <li>The project manager and heavy equipment operators shall perform daily pre-work equipment inspections for cleanliness and leaks. All heavy equipment operators shall be postponed or halted should a leak be detected, and shall not proceed until the leak is repaired and the equipment that would be operated in or near water.</li> <li>Fueling of land-based vehicles and equipment shall take place at least 50 feet away from the water, preferably over an impervious surface. Fueling of vessels shall be done at approved fueling facilities.</li> <li>Turbidity and siltation from project-related work shall be minimized and contained through the appropriate use of erosion control practices, effective silt containment devices, and the curtailment of work during adverse weather and tidal/flow conditions.</li> <li>All wastes shall be collected and contained for proper disposal at approved upland disposal sites appropriate for the material(s).</li> <li>When removing piles and other similarly treated wood, containment curtain must fully enclose the work area. Wood debris, oils, and any other materials released into lake waters must be collected, removed, and poperty disposed of at approved disposal sites.</li> <li>All in- and over-water wood cutting would be limited to the minimum required to remove the subject wood component, and all cutting work should be enclosed within floating containment curtain.</li> <li>When removing piles, no actions shall be taken that would cause adhering sediments to return to lake waters.</li> <li>Above-water containment shal</li></ul>	Datum: CORPS OF ENGINEERS 1919       Applicant: Henry Residence         NE Quarter Of Section 30, Township 24, Range 05       Applicant: Menry Residence         Adjacent Owners:       6802 96TH AVE SE         STIVERS JEAN GILLILAND-TTEE       NEDERMAN CHRISTOPHER A         Created:       Created:
	e (8) new steel piles, remove (1) existing mooring pile, construct a 233 SQFT extension, repair e 12.44 cu yd concrete slabs, install a new cove with stairs, and permit (2) existing boat lifts.	US-2022-XXX PAGE 7 OF 13

# MITIGATION PLAN





#### Notes:

- 1. Shrubs are show, and shall be planted, at least five feet on center. Trees are show, and shall be planted, at least ten feet to center.
- 2. The property owner will implement and abide by the shoreline planting plan. The plants shall be installed before or concurrent with the work authorized by this permit. A report, as-built drawing and photographs demonstrating the plants have been installed or a report on the status of project construction will be submitted to the U.S. Army Corps of Engineers, Seattle District, Regulatory Branch, within 12 months from the date of permit issuance. This reporting requirement may be met by completing and submitting a U.S. Army Corps of Engineers approved Report for Mitigation Work Completion form.
- 3. The property owner will maintain and monitor the survival of installed shoreline plantings for five years after the U.S. Army Corps of Engineers accepts the as-built report. Installed plants shall achieve 100% survival during monitoring Years 1 and 2. Installed plants shall achieve at least 80% survival during monitoring Years 3, 4 and 5. Percent survival is based on the total number of plants installed in accordance with the approved riparian planting plan. Individual plants that die will be replaced with native riparian species in order to meet the survival performance standards.
- 4. The property owner will provide annual monitoring reports for five years (Monitoring Years 1-5). Each annual monitoring report will include written and photographic documentation on plant mortality and replanting efforts and will document whether the performance standards are being met. Photos will be taken from established points and used repeatedly for each monitoring year. In addition to photos at designated points, photo documentation will include a panoramic view of the entire planting area. Submitted photos will be formatted on standard 8 1/2 x 11" paper, dated with the date the photo was taken, and clearly labeled with the direction from which the photo was taken. The photo location points will be identified on an appropriate drawing. Annual shoreline planting monitoring reports will be submitted to the U.S. Army Corps of Engineers, Seattle District, Regulatory Branch, by November 31 of each monitoring year. This reporting requirement may be met by completing and submitting a U.S. Army Corps of Engineers approved Mitigation Planting Monitoring Report form.

## **PROPOSED PLANTING SPE**


SYMBOL	LATIN NAME	C
	Thuja plicata	W
	Pinus contorta v contorta	
	Rosa nutkana	
	Philadelphus lewisii	

PLANTS: Shrubs to be installed 5ft on center and trees to existing plants for credit have been established for 5 year


BUILTBY
SEABORN
• ESTD 1947 •

Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119 Office: 206-236-1700 ext. 3 www.seabornpiledriving.com Scope of Work: We propose to drive (8) new steel piles, remove (1) existing mooring pile, cons 74 LnFt of existing bulkhead, remove 12.44 cu yd concrete slabs, install a new cove with stairs


				King County Lake Washington		122 4:28 PM Zion
OS LOCIENING BRES AND OR LOCIENING BRES AND OR WALS BREST AND ALLOOP OR WALS OF FREE ON				County: Location:		Last Updated: 8/2/2022 4:28 PM Zion
+3°+ SHRUB AND GROU PLANTING DETAIL					Mercer Island, WA 98040	
ECIES/QUA		ITIES		Applicant:		Created:
COMMON NAME	QTY	SIZE				IER A
Vestern Red Cedar	1	3 ft		9 24, Range 05		N CHRISTOPH AVE SE 98040
Shore pine	1	3 ft		ERS 191 wnship 2		NIEDERMAN CHRI 6800 96TH AVE SE
Nootka Rose	1	1 Gallon		NGINEE 1 30, To		H
Mock Orange	2	1 Gallon		S OF E Section	wners:	-ILAND-TTI 38040
o be installed 10ft on rs or more on the pro		All propose	d	Datum: CORPS OF ENGINEERS 1919 NE Quarter Of Section 30, Township 24	Adjacent Owners	STIVERS JEAN GILLILAND-TTEE 6810 96TH AVE SE 98040
struct a 233 SQFT ex , and permit (2) exist				SHEET	8.0	
				NWS-20 PAGE		



; E	ES/QUANT	King County Lake Washington	M Zion		
	COMMON NAME	QTY	SIZE		_ast Updated: 8/2/2022 4:28 PM Zion
	Commom Chicory	2	~3ft	County: Location:	: Updated: 8/2
	Orange Daylily	4	~2ft		_
	Blue Fescue	N/A	~ 1ft	Henry Residence 6802 96TH AVE SE Mercer Island, WA 98040	
	ruct a 233 SQFT ex			Datum: CORPS OF ENGINEERS 1919 NE Quarter Of Section 30, Township 24, Range 05	Adjacent Owners:       Image: Structure of the stru
	and permit (2) exist			SHEET	9.0
				NWS-2022 PAGE 9 0	




# DETAILS - TRACK



	NWS-2022- PAGE 11 O	
struct a 233 SQFT extension, repair s, and permit (2) existing boat lifts.	SHEET	2
SLEEPER, PER PLAN (TYP) COATED PL CL BOLTS CL BOLTS CL BOLTS COUNTERSINK BOLT: 1" MAX COUNTERSINK BOLT: 1" MAX EDGE BEAM PER PLAN (DOES NOT CONTINUE @ SIM CONDITION	Datum: CORPS OF ENGINEERS 1919 NE Quarter Of Section 30, Township 24, Range 05 Adiacont Ownors: Adiacont Ownors:	AUJACCTIL OWITCI S. STIVERS JEAN GILLILAND-TTEE NIEDERMAN CHRISTOPHER A 6810 96TH AVE SE 98040 6800 96TH AVE SE 98040 Created:
	dence County: King County <sup>JE SE</sup> Location: Lake Washington <sup>WA 98040</sup>	Last Updated: 8/2/2022 4:28 PM Zion


# DETAILS - TRACK

		TACK WELD BOLTS PER S1/SHEET 11.0 ANGLE TO PLATE BOLTS PER S1/SHEET 11.0 3/16 PL PER S1/SHEET 11.0 3/8" ANGLE, PER PLAN 9 4 6"- 51/SHEET 11.0 9 4 9 51/SHEET 11.0 9 10 9 10 9 10 9 10 9 10 9 10 9 10	WF PILE CAP PER PLAN (4)
S1 DETAIL NOT IN USE		S2 ANGLE TO PLATE - TYP	S3)BEAM SADDLE BRAC
(S4)DETAIL NOT IN USE		(S5)DETAIL NOT IN USE	(S6) DETAIL NOT IN USE
BUILT BY SEABORN · ESTD 1947 ·	Seaborn Pile Driving 1080 W Ewing St Seattle, WA 98119 Office: 206-236-1700 ext. 3 www.seabornpiledriving.com	ope of Work: We propose to drive (8) new steel piles, remove (1) e LnFt of existing bulkhead, remove 12.44 cu yd concrete slabs, inst	existing mooring pile, con




# DETAILS- COVE

# COVE AND BEACH SECTION VIEW



# (S1)BULKHEAD W/ COVE AND STEPS



	NWS-2022-XXX PAGE 13 OF 13	
struct a 233 SQFT extension, repair s, and permit (2) existing boat lifts.	SHEET 13.0	
	Datum: CORPS OF ENGINEERS 1919 NE Quarter Of Section 30, Township 24, Range 05	Adjacent Owners: STIVERS JEAN GILLILAND-TTEE NIEDERMAN CHRISTOPHER A 6810 96TH AVE SE 98040 6800 96TH AVE SE 98040
- PROPOSED OHWM	Applicant: Henry Residence 6802 96TH AVE SE Mercer Island, WA 98040	Created:
	County: King County Location: Lake Washington	Last Updated: 8/2/2022 4:28 PM Zion
	y ington	u

## Appendix B: Site Photographs



Photo 1 - Existing dock looking waterward.



Photo 2 - Existing dock looking landward.



Photo 3 - Existing shoreline conditions north of dock showing cove and bulkhead.




Photo 4 - Existing shoreline conditions south of dock.



Photo 5 - Shoreline conditions north of the site.



Photo 6 - Shoreline conditions south of the site.