



Front Water Services, Inc.

8661 Dallas Avenue
Seattle, Washington 98108

Phone (206) 757-0301

9 November 1994

Mr. Mr. Nithington
8000 SE 20th Ave
Mercer Island, WA 98040

Re: Pumping and wash out of home heating oil tank

To Whom It May Concern:

This Letter confirms that Frontwater Services Inc. Pumped the remaining liquids from oil tank. Then the interior of the tank was washed and pumped three (3) times.

The work was accomplished at the above address.

Sincerely,

Peter P Hofmann
General Manager

Job # 94-1298

9411280757

OF 500 BOSTON AVENUE, NEW YORK, NY 10022-4242



Front Water Services, Inc.

8661 Dallas Avenue
Seattle, Washington 98108

Phone (206) 767-0301


CLOSE-OUT DOCUMENT

18 November 1994

WORK ACCOMPLISHED:

- Tank pumped and washed on 9 November 1994.
- Tank filled with cement slurry on 9 November 1994.
- Tank close out completed on 18 November 1994.

SKETCH SHOWING APPROXIMATE LOCATION OF TANK:



9411280757

NOT TO SCALE:

Front Water's Reference
 Job Number: 94-1298
 Date of Completion: 18 November 1994

Homeowner Signature:
Theresa N. [Signature]
 Date: NOV 22 1994

Wilmington, H.W.

H 645230-22B-00

1034RA

Mercer Park Add.

lots 28 + 1/2 29

105 FT of W 195 FT of BLK 28-29-30

9411260757